

**SINUMERIK 3M**  
Basic Version 4C

**Programming  
Guide**

# **SINUMERIK**

**Edition 08.88**

To: Library (0000000)

DOCUMENT CHANGE

Date: 90/08/03

Change no:

001574

Control Document no:

3.05.4

Please make the following changes to the above document and then sign  
and return the change Confirmation below.

Change type:

New issue of this document - please add to your collection

Ensure the top half of this form is either stapled into the document  
or filed behind the Amendment Record Sheet.  
Please return the lower half after signing it.

# SINUMERIK 3M Basic Version 4C

Programming Guide

Edition 08.88

SIEMENS  
SERVICE CENTRE  
LIBRARY

ACCESS NO.	1647 b
SHELF NO.	NC 3M PG

Subject to change without prior notice

Functions extending beyond the scope of this Description may be capable of operating on the controller. However, we accept no responsibility for such functions for new equipment or equipment which has been serviced.

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

© Siemens AG 1989

General

---

0

Program format

---

1

Path information

---

2

Preparatory functions

---

3

Miscellaneous and auxiliary functions S, T, M, H

---

4

R Parameters

---

5

Programming aids

---

6

Cycles

---

7

Appendix

---

8

# SINUMERIK®-Documentation

## Key to Editions

The Editions listed below have been published prior to the current Edition.

The column headed "Amendments" lists the amended sections, at all times with reference to the previous Edition.

Edition	Order No.	Amendments
08.88	6ZB5 410-0AM02-0BA0	New Edition

# Table of contents

	Page
0	General introduction to Programming Instructions ..... 0-1
1	Program format ..... 1-1
1.1	Punched tape code ..... 1-1
1.2	Character set ..... 1-2
1.3	Word structure ..... 1-3
1.4	Block structure ..... 1-5
1.5	Leader ..... 1-7
1.6	Comments ..... 1-7
1.7	Part program ..... 1-9
1.8	Subroutines ..... 1-10
1.9	Subroutine call, subroutine nesting ..... 1-12
1.10	Punched tape formats ..... 1-13
1.11	Punched tape format for erasing programs ..... 1-15
2	Path information ..... 2-1
2.1	Axis commands ..... 2-1
2.2	Mirroring ..... 2-3
3	Preparatory functions ..... 3-1
3.1	G90/G91 Absolute and incremental dimension programming ..... 3-2
3.2	G00 Rapid traverse ..... 3-3
3.3	G01 Linear interpolation ..... 3-4
3.4	G02/G03 Circular interpolation ..... 3-5
3.4.1	Circular interpolation using interpolation parameters ..... 3-6
3.4.2	Example for circular interpolation using interpolation parameters ..... 3-8
3.4.3	Circular interpolation by specifying the radius ..... 3-9
3.4.4	Example of circular interpolation by specifying the radius ..... 3-9
3.4.5	Helical interpolation ..... 3-10
3.5	G 33 Thread cutting ..... 3-11
3.5.1	Constant lead tapered threads ..... 3-13
3.5.2	Feed direction ..... 3-14
3.5.3	Variable lead thread ..... 3-15
3.5.3.1	Variable lead thread without G34, G35 ..... 3-15
3.5.3.2	Thread cutting G34 (increasing lead) ..... 3-15
3.5.3.3	Thread cutting G35 (decreasing lead) ..... 3-15
3.5.4	Multiple thread ..... 3-16
3.5.4.1	Multiple thread via axial starting point offset ..... 3-16
3.5.4.2	Multiple thread with spindle-specific starting angle offset (Basic control 4B, option E35) ..... 3-16
3.5.5	Thread cutting with a boring bar ..... 3-17

3.6	G60 Exact stop (Reset state 10th G group) .....	3-19
3.7	G63 Tapping with a floating tap holder .....	3-20
3.8	G64 Continuous path control .....	3-20
3.8.1	G62 Contour Machining (rounding of block transition by reduced speed) ..	3-20
3.9	G04 Dwell time .....	3-21
3.10	G70/71 Input systems .....	3-22
3.11	Zero offsets (ZO) .....	3-24
3.11.1	G54/G55/G56/G57 Settable zero offset .....	3-25
3.11.2	G59 Programmable zero offset .....	3-27
3.11.3	G53 Cancelling the zero offsets .....	3-29
3.12	G94/G95 Feed F .....	3-30
3.13	G17/G18/G19 Machining plane selection .....	3-34
3.14	Tool offset .....	3-35
3.15	G40/G41/G42 Intersectional cutter radius compensation .....	3-37
3.16	G43/G44 Tool length offset (positive, negative) .....	3-43
3.17	Milling of cylindrical contours G92 P .....	3-45
3.18	G10/G11 Polar coordinate programming .....	3-48
3.19	G36, G37, G38 TRANSMIT coordinate transformation .....	3-51
3.20	Programmable turning of coordinates .....	3-56
3.21	Dynamic smoothing exponent for threads .....	3-59
<b>4</b>	<b>Miscellaneous and auxiliary functions S, T, M, H .....</b>	<b>4-1</b>
4.1	S word .....	4-1
4.2	Tool function T .....	4-2
4.3	Miscellaneous functions M .....	4-2
4.4	Auxiliary functions H .....	4-4
4.5	Rapid switching and auxiliary functions .....	4-4
<b>5</b>	<b>R Parameters .....</b>	<b>5-1</b>
5.1	Parameter definition .....	5-2
5.2	Assigning parameters in a program .....	5-2
5.3	Operations with parameters .....	5-3
5.4	Parameter chaining .....	5-5
5.5	Programming examples using parameters .....	5-7
5.6	Empty buffer store, L99; @ 31 .....	5-10
5.7	Branch conditions .....	5-11
5.7.1	@ 00 Unconditional jump .....	5-11
5.7.2	@ 01; @ 02; @ 03 Conditional jump .....	5-13
5.7.3	Concluding example for unconditional and conditional jumps .....	5-15
5.8	@ 10 "Square root" .....	5-16
5.9	@ 15 "Sine" .....	5-17
5.10	@ 18 "Arctan" .....	5-18
5.11	@ 20 "Load address parameter" .....	5-19
5.12	@ 90 - @ 93 "Address parameter" .....	5-21
5.13	@ 29 "Load/read from system memories" .....	5-22
5.14	@ 28 "Selecting the R parameter group" (only basic version 4C) .....	5-26



6	Programming aids .....	6-1
6.1	Automatic insertion of chamfers and radii .....	6-2
6.1.1	Miscellaneous and auxiliary functions in linked blocks .....	6-3
6.1.2	Example: Rectangular pattern .....	6-4
6.2	Blueprint programming (Basic control 4B, 4C) .....	6-5
6.2.1	Contour cycle programming .....	6-6
6.2.2	Operation of the function F, S, T, H, M in contour cycles .....	6-11
6.2.3	Chaining of blocks .....	6-12
6.2.4	Examples .....	6-13
6.2.5	Miscellaneous and auxiliary functions in chained blocks .....	6-15
7	Cycles .....	7-1
7.1	Drilling/Boring cycles G81 - G89 .....	7-1
7.2	Examples of limitations in calling boring cycles .....	7-8
7.2.1	Calling boring cycles in a subroutine .....	7-18
7.3	Listing of the boring cycles .....	7-19
7.3.1	Boring cycles G80 - G89 for boring axis Z (basic controls 0,1,2) .....	7-19
7.3.2	Boring cycles G80 - G89 for boring axis Z (basic controls 3, 4, 4B, 4C) .....	7-21
7.3.3	Boring cycles G80 - G89 with variable boring axes (basic controls 3, 4, 4B, 4C) .....	7-23
7.4	Keyway milling pattern L94 .....	7-25
7.5	Milling rectangular shape, subroutine L95 .....	7-26
7.6	Milling circular shape .....	7-28
7.7	Drilling/boring patterns .....	7-30
7.7.1	Subroutine: Boring pattern L97 .....	7-30
7.7.2	Subroutine: Boring/drilling pattern L93 (up to basic control 4B) Subroutine: Boring/drilling pattern L904 (basic control 4C) .....	7-31
7.8	Subroutine: Milling pattern for elongated hole L98 .....	7-32
8	Appendix .....	8-1
8.1	Cutter radius compensation .....	8-1
8.1.1	Selecting the CRC .....	8-1
8.1.2	CRC in the program .....	8-2
8.1.3	Repetition of G function already selected (G41/G42) with same offset number .....	8-6
8.1.4	Cutter radius compensation deselection .....	8-7
8.1.5	M00, M02 and M30 with CRC selected .....	8-9
8.1.6	CRC with combination of different block types .....	8-10
8.1.7	Special cases for CRC .....	8-14

8.2	Input systems, diagrams and tables .....	8-17
8.2.1	Incorrect input of the interpolation parameters I, J, K .....	8-17
8.2.2	Reference points .....	8-18
8.2.3	Path calculation .....	8-19
8.2.4	Rotational feedrate limits .....	8-20
8.2.5	Input formats .....	8-21
8.2.6	Code tables .....	8-22
8.3	Program key .....	8-23
8.4	Special cases .....	8-26
8.4.1	Special case "Delete distance to go" .....	8-26

## 0.1 General introduction to the programming guide

This programming guide applies to SINUMERIK 3M in the basic versions 0, 1, 2, 3, 4, 4B and 4C.

The following assumptions are made in the programs used in this programming guide.

1. The decimal point is written even when it is automatically generated.
2. Block construction is in accordance with DIN 66024, DIN 66025, DIN 66217, ISO R 1056, ISO 1057, and ISO R 1058.
3. The programming examples are written in ISO code.  
All geometric values are metric.  
For conversion into inch see section 8.2.5 and 3.10.
5. The max. values given are limit values for the control.  
They can be limited in practice by the machine, interface, and input/output devices.
6. This programming guide is designed for the maximum functional range of the control basic version 4. Restrictions in the functions for the basic versions 0, 1, 2 and 3 are given in the respective footnotes.

7. For better understanding preparatory functions are programmed even if these are commands with reset position.
8. The contents of this programming guide are included in the fold-out program key as an aid to finding the respective section.
9. Functions extending beyond the scope of this guide may be capable of operating in the controller. However, no claims are made with respect to such functions when first delivered or on servicing.

We reserve the right to alter this guide on the basis of technical modifications.

## 1. Program format

### 1.1 Punched tape code

The data on the punched tape is coded according to strictly defined guidelines. Each hole combination defines a unique character. Two punched tape codes are permissible.

DIN 66025 (ISO)

EIA-RS 244-B

The control automatically recognizes the correct format. The coding format is determined on reading the first % or EOR. Individual punched tapes must be coded in one of the allowable codes. It is not permissible to change codes within the same tape nor is it permissible to splice tapes together using different codes. Failure to observe the aforementioned will cause the control to signal a character parity error.

The characters in each code are defined to have even or odd parity.

ISO even number of holes

EIA odd number of holes

The criterion of even or odd number of holes is used from the second character of the program onwards for character parity check. Simple errors can be recognized 100%.

The block parity check monitors for an even number of characters within a block of data. A block with an odd number of characters is made even by writing the characters "HT" or "SP". Block parity check can be deselected.

As an additional tape read check; the control compares the program previously read into the memory through a second read-in.

If a character mismatch occurs tape read is halted and a read error is displayed on the control operator panel.

The word address assignment is defined by DIN 66025 (ISO).

7. For better  
programm  
positi

the punched tape code are read by the  
executable block is assembled using only  
characters.

8. Th

Address characters A, B, C, D, F, G, H, <sup>1)</sup>I, J, K, L,  
M, N, P, R, S, T, U, V, W, X, Y, Z

Digits 0, 1, 2, 3, 4, 5, 6, 7, 8, 9

Alphanumeric character 0 (for inputting T0 = tool offset)

Printable special characters %, (, ), +, -, /, ., @

Non-printable characters  
HT Tabulator  
SP Space  
DEL Delete  
CR Carriage return  
LF Line feed

#### INPUT READ

The following characters are neither processed nor stored

HT

SP

DEL

CR (CR LF sequence is arbitrary)

#### OUTPUT TO PRINTER/PUNCH

The following characters are generated.

SP (following every word)

CR (is generated and output twice following LF)

LF is displayed as an \*

1) for basic control 4

### 1.3 Word structure

A Word consists of an address letter and a series of digits with or without a sign (Address notation).

The word structure and therefore the input format are exactly and precisely defined.

Address notation in accordance with ISO/R1056,  
ISO R1057, ISO R 1058, DIN 66027,  
DIN 66025, DIN 66217, EIA R 274,  
variable length of words and blocks

The metric values are as follows:

Basic control 0, 1, 2:   %04 N04 G02 D02 XL+043 YL+043  
                          ZL+043 ID043 JD043 KD043 F05  
                          S04 T04 R2 RL+043 L4 PD033 M02

Basic control 3:       %04 N04 G02 D02 XL+053 YL+053 ZL+053  
                          ID053 JD053 KD053 F05 S04 T04 R2  
                          RL+053 L4 PD033 M02

Basic control 4, 4B:   %04 N04 G02 D02 XL+053 YL+053 ZL+053  
                          ID053 JD053 KD053 F05 S04 T04 H04  
                          R2 RL+053 L5 PD033 M02 AL035

Basic control 4C:      %04, N04 G02 D02 XL+053 YL+053 ZL+053  
                          ID053 JD053 KD053 F05 S04 T04 H+04 R2  
                          RL+053 L5 PD033 M+02 AL035

Explanations:

First character	Address	
Second character	L	absolute/incremental
Second character	D	incremental
Symbol	+	Absolute dimension with positive or negative sign
First digit	0	leading zeros not required: variable word length
Second digit	decade	part of number
Second and third digit	decade	part of number (Coordinate values X, Y, Z, I, J, K in mm)
Symbol	*	Block end

Word examples:

X + 2345.531	G60
X    Address	G    Address
+    Sign	
2345 Digits	60 Digits
.    Decimal point	
531 Digits	

Value	Decimal point entry:
1 $\mu\text{m}$	0.001 or .001
10 $\mu\text{m}$	0.01 or .01
100 $\mu\text{m}$	0.1 or .1
1000 $\mu\text{m}$	1. or 1
10200 $\mu\text{m}$	10.2
100000 $\mu\text{m}$	100. or 100

Decimal point entry is possible using the following addresses:  
X, Y, Z, A, B, C, U, V, W, I, J, K, P, R, F (mm/rev) see 8.2.5.




## 1.4 Block structure

A block consists of several words terminated by the "End of Block" character.

Block length is variable and can have a max. of 120 characters. A total number of 80 characters can be displayed at one time.

### An example of a block



The block sequence numbers need not necessarily be sequentially numbered. A numbering sequence can be interrupted arbitrarily, e.g. an edited or inserted block may have a sequence number several orders of magnitude higher than the preceding sequence number.

Program operations not necessary for every program run, such as guaging, may be identified by the block delete symbol "/". These program sections will be ignored by the control when the "Block Skip" switch has been activated.

The "/" character is placed in front of the block number:

/N.... Skippable block

The blocks skipped must have the same start and end points, otherwise the program will execute incorrectly, when activating or deactivating the "block skip" switch.

## 1.5 Leader

The leader is used to differentiate between tapes. All characters are valid in the leader except:

- %; The automatic code recognition is initiated by % (ISO).
- EOR; The automatic code recognition is initiated by EOR (EIA).

During execution of the program, the leader is skipped by the control. The leader is not stored.

## 1.6 Comments

Program blocks may be clarified by using comments. It is possible for the operator to view comments on the screen/display.

Within a comment all characters except % and LF are legal. But no block number used in the program may be included, because the bracket contents are read for jump functions and for block search.

A comment may contain a maximum of 29 characters. If this is insufficient, several comments can be programmed one after another.

Example:


N25 G70 (all following)  
(Geometric values in inches)

Incorrect

Y	( FLANGE )	100.
Y 100.	( FLANGE )	R01

Correct

X100.	( FLANGE )	Z 200.
X100. R01	( FLANGE )	Z 200.



A comment may not be placed between an address and its dimension or between a word and its associated parameter.

## 1.7 Part programs

A part program describes the execution of a machining process and contains the part program itself with possible subroutines and/or cycles called.

A total number of 200 part programs and subroutines \*) can be stored in the program memory.

Program start with:

only one part program in  
the program memory

more than one part program  
in the program memory

% LF

```
N5 G91 G01 X50. F100 LF
N10      Y100.      LF
N15      X-30.      LF
N20      Y-10.      LF
N25      M30        LF
```

% 1357 LF

```
N5 G91 G01 X50. F100 LF
N10      Y100.      LF
N15      X-30.      LF
N20      Y-10.      LF
N25      M30        LF
```

The program number may contain a maximum of 4 digits.

\*) With basic control 3:

max. 100 part programs and sub-  
routines

With basic controls 0, 1, 2: max. 20 part programs and sub-  
routines

## 1.8 Subroutines

Repetitive patterns and function cycles can be stored as subroutines which can be called arbitrarily by the part program or manual data input.

The subroutine definition is designated by 2 or 3 decade number and 2 trailing zeros. Part programs and subroutines can be filed in memory simultaneously in the following quantities:

Basic controls 0, 1, 2:	20 part programs and subroutines
Basic control 3:	100 part programs and subroutines
Basic control 4:	200 part programs and subroutines

L <u>41200</u>	- Subroutine 412
	Always without block no. and M17
N1 G91 G01 Y-10. F100. LF	Definition of path information,
N5 Y... X10. LF	dimensions, directions, and
.	feeds.
N10 X... LF	
N15 M17 LF	- End of subroutine. M17 is
	written in the last block.

The subroutine call is made within a part program or a subroutine via the address L. The subroutines can be nested three-deep in the part program.

The cycle call is as follows for basic control 4:

L 412 05 5-digit call with number of passes

Number of passes must be input as 2 digits (01...99).  
Subroutine number can be input as 3 digits  
(001...999) or must be input as 2 digits (01...99).

L 412 3-digit call without number of passes

Omission of the number of passes means that the  
subroutine is only executed once.

Subroutine number 2-digit or 3-digit

The cycle call is as follows for basic controls 0, 1, 2, 3:

L 41 05 4-digit call with number of passes

Number of passes must be input as 2 digits (01...99).  
Subroutine number must be input as 2 digits (01...99).

L 41 2-digit call without number of passes


Omission of the number of passes means that the  
subroutine is only executed once.

Subroutine number 2-digit (01...99)

The subroutine call must not appear in the same block as M02,  
M03 or M17. Subroutines L80-L99 and L900-L999 <sup>1)</sup> are reserved  
for cycles. Automatic block search is possible to the 1st sub-  
routine level.

1) In the case of basic controls 0, 1, 2, 3: Only L91 - L99

# 1.9 Subroutine call, subroutine nesting



1) only with basic control 4



1.10 Punched tape format

Subroutine % {SR} LF / L 2300 LF / N1 ....LF / N2 M17 LF

Leader            Rewind stop and subroutine 23    End of subroutine  
Block start

L 2400 LF / N1 .... LF / N2 (Drilling cycle) .... LF / N .. M17 LF

Subroutine 24                                      (Comment)                                      End of  
subroutine

L 2500 LF / N.. ....LF/N.. ....LF / N.. M17 LF / N..M02 or M30 LF

Subroutine 25                                      End of sub-                                      End of sub-  
routine                                      routine block

Program shaft / % {1234} LF /(Gauging sequence)

Leader                      Part program                      (Comment)  
1234

N.. ... LF / N.. ... LF / N200 M02 or M30 LF

Part program                                      Part program end

% T0 LF / G92 D01 .... LF / G92 D02 .... LF / M02 or M30 LF

Tool offsets                                      End of tool  
offset load

% TE LF / N... S...                      LF / N... S...                      LF / M02 or M30 LF

Machine data                                      End of machine data  
Test data                                      block

characters between brackets may be omitted.

SR Subroutine

← % R LF | R00 12345.678 LF | R01 5LF ... | M02 or M30 LF →  
R parameter <sup>1)</sup> R parameter block end

← % H LF | H00 12345.678 LF | H01 5LF ... | M02 or M30 LF →  
Background memory <sup>1)</sup> Background memory block  
end

The input sequence for the above tape is arbitrary.

The classification of the memory in part programs and sub-routines takes place automatically.

The tool offset is inserted in the corresponding memory area with the T0 (Tool Offset) identifier.

1) only with basic control 4C

## 1.11 Punched tape format for erasing programs

With this function, main programs and subroutines can be erased in any sequence via the universal input/output interface.

ERASE PROGRAM	- Leader
% CL LF	- Identifier (Clear)
% 1234 LF	- Erase parts program %1234
% 1 % 1200 LF	- Erase parts programs %1 to %1200
L10 LF	- Erase subroutine L10
L11 L79 LF	- Erase subroutines L11 to L79
L81 LF	- Erase subroutine L81
M30 or M02 LF	

### Example:

% CL LF    % 1 LF    L55 LF            % 1 % 1200 LF            L11 L79 LF

erase programs	erase program % 1	erase subroutine L55	erase programs % 1 to % 1200	erase subroutines L11 to L79
-------------------	-------------------------	----------------------------	------------------------------------	------------------------------------

L81 LF            M30 or M02 LF

erase subroutine L81	End of erase block
----------------------------	-----------------------

### Caution:

Subroutines L80 - L99 and L900-L999 1) must be erased individually.

These subroutines cannot be erased if cycle inhibit is on 1).

1) with basic control 4, 4B, 4C

## 2. Path Information

### 2.1 Axis commands

The address of the axis command specifies the axis (X, Y, Z) in which the dimension should be traversed. The addresses A, B, C, U, V and W can be used for the 4th axis.

The 4th axis may also be used as a rotary axis. This is set via a machine parameter.

The dimension values for the rotary axis must always be programmed 3 positions to the right of the decimal, even though the rest of the dimension input is in the  $10^{-4}$  inch system.

The rotary axis can be programmed to max.  $\pm 27 \times 360$  degrees ( $9720.000^\circ$ ). <sup>1)</sup>

The rotary axis can be programmed to max.  $\pm 256 \times 360$  degrees ( $\pm 92159.999^\circ$ ). <sup>2)</sup>

With the "Modulo 256" function the rotary axis can be turned endlessly. The actual value is reset to zero after  $\pm 256 \times 360$  degrees ( $\pm 92159.999$  degrees). In a single block the rotary axis can be programmed to a max. value of  $\pm 256 \times 360$  degrees.

Several axes can be defined as endless rotary axes simultaneously. <sup>3)</sup>

With the "Modulo 1 rev" function, rotary axes can turn endlessly.

The actual value is reset to zero degrees after  $\pm 1$  times  $360^\circ$ .

Several axes can be defined as endless rotary axes simultaneously. <sup>4)</sup>

1) with basic controls 0, 1, 2

2) with basic controls 3, 4

3) with basic control 4

4) With basic control 4B, 4C

## Fourth axis

The fourth axis may be defined as being parallel to the X, Y, or Z axis via a machine parameter.

Which of the parallel axes is the secondary motion axis (e.g. Z or 4th axis) is determined by a signal from the interface. This signal may not change state after the start of the program.

Circular interpolation between parallel axes is not possible. The secondary axis can be used in place of its primary axis for circular interpolation.

Only the 4th axis can be used as a rotary axis. <sup>1)</sup>

1) with basic controls 0, 1, 2, 3

## 2.2 Mirroring

The axes defined as primary axes during commissioning can be mirrored by acknowledging programmed auxiliary functions via the interface. The following values are inverted or exchanged during block preparation.

For the primary motion axes the following holds true

- Sign of the programmed values
- Rotation direction G02 → G03; G03 → G02
- Single axis mirrored in the CRC plane; G41 → G42; G42 → G41.
- Two axes mirrored in the CRC plane: G41 → G41; G42 → G42, G02 → G02, G03 → G03

The following values are not mirrored:

- Length offset dimensions
- Zero offsets

The workpiece is always mirrored when mirroring the primary motion axes.

The "mirror" interface signal is transmitted to the NC via the buffer memory (see section 5.6).


Example: Mirroring selection

```
N10 G90 G54 G00 X0 Y0
N20 Z30.
N30 G1 Z0.F500
N35 M.. (X-axis mirroring)
N36 G04 F.. (dwell time longer than 1.2 times max. PLC cycle time)
N37 @ 31
N40 X50. Y50.
N45 M.. (deselect axis mirroring)
N46 G04 F..
N47 @ 31
N50 G0 G53 Z0.
N60 G53 X0. Y0.M30
```

Example: Mirroring the X axis

Mirrored workpiece

Programmed workpiece



- M = machine zero  
 W = workpiece zero  
 P = cutter radius  
 NV = zero offset
- workpiece contour  
 - - - - the cutter centre path

If the control is equipped with the cutter radius compensation function (option), only the workpiece contour need be programmed.

```

N1 G00 G90 G17 G64 G41 D01 X0. Y0. M03 S56 LF
N2 G01 Y20. LF
N3 X15. Y35. LF
N4 X35. LF
N5 G03 X50. Y50. I0. J15. LF
N6 G01 X...
    
```

### 3. Preparatory functions

The preparatory functions describe the manner in which the machine slide is to move, the method of interpolation, the dimension system, the timed delay of program execution, and the activation of specific operational modes in the control.

The preparatory functions are divided into groups (see program key).

A programmed block may contain only one preparatory function from each group, otherwise the last programmed function of a group is valid.

The default states are valid when the control is switched on, reset, or at the end of program. It is not necessary to program the default preparatory functions.

Modal preparatory functions can only be overwritten by other preparatory functions from the same function group. Hence they remain effective until another code from the same group is selected.



### 3.1 G90/G91 Absolute and incremental dimension programming

#### Absolute dimensioning G90 (Reset state 12th G-group)

In absolute dimensioning all dimensions are in reference to the workpiece zero.

The dimension denotes the end position in the coordinate system.

#### Incremental dimensioning G91

An incremental dimension defines the path to be traversed with respect to the present position. Incremental dimensioning is advantageous in subroutine programming.

A zero offset is always active with absolute and incremental programming.


(See also section 8.2.3).

### 3.2 G00 Rapid traverse

A block programmed with G00 will traverse in a straight line at the highest possible speed (rapid traverse) to the programmed position. The control monitors each axis traverse rate so that the maximum allowable rate (machine parameter) is not exceeded.

The preparatory function, rapid traverse (G00), includes automatic exact stop.

Programming G00 does not cancel the feed function. The feed function will still be active when programming a G01 following a G00.



W = workpiece zero

#### Absolute dimension programming

N... G00 G90 X60. Y40. LF Tool traverses from P1 to P2.

#### Incremental dimension programming


N... G00 G91 X40. Y30. LF Tool traverses from P1 to P2.

### 3.3 G01 Linear interpolation (reset state 1st G-group)

The tool traverses with the programmed feed rate F in a straight line to the programmed end point.

Paraxial and straight line path movements at any angle are possible.

With linear interpolation 2 out of 4, or with 3D interpolation 3 out of 4 axes can be traversed <sup>1)</sup>.



#### Incremental dimension programming

```
N3 G91 G94 G01 X-25. F1000 LF Feedrate programming
N4           X-25. Y10. LF at 1000 mm/min
```

#### Absolute dimension programming

```
N3 G90 G94 G01 X50. Y25. F1000 LF
N4           X25. Y35. LF
```


1) with basic controls 3, 4

### 3.4 G02/G03 Circular interpolation

The interpolation parameters together with axis commands determine the circle or arc. The starting point "KA" is determined by the previous block. The end point "KE" is fixed by the axis values of the plane in which the circular interpolation is programmed. The circle centre point "KM" is determined.

- a) either through the I, J and K vectors, sign dependent, from a range of 0 to  $360^{\circ}$ . The sign results from the coordinate direction from the start point to the centre point.
- b) or directly through the radius P 1)  
+P Angle less than or equal to  $180^{\circ}$   
-P Angle greater than  $180^{\circ}$


Radii should not be programmed when the angle to be traversed is  $0^{\circ}$  or  $360^{\circ}$ . In these cases the full circles must be programmed using the interpolation parameters I, J, and K.



Circular interpolation is possible in 2 out of 4 axes

- 1) with basic control 4

The direction in which the arc is traversed is determined by G01 or G03.



A right-hand system in the 3 primary axes is achieved with the following axis combinations:

X...	Y...	->	G17
Z...	X...	->	G18
Y...	Z...	->	G19

#### 3.4.1 Circular interpolation using interpolation parameters

The starting point of the circle or arc is determined by the previous block. The end point is fixed by the respective axis values.

The circle centre is determined through the interpolation parameters.

Increment (+ sign)  
from circle start point  
to circle centre point

I parallel to X axis  
J parallel to Y axis  
K parallel to Z axis

If only one axis coordinate is programmed, the value belonging to the primary axis of the selected plane (G17, G18, G19) is used as secondary axis coordinate. If the signal "4th axis = primary axis" is active, then this value is used according to the selected plane.

The 4th axis may be defined using machine parameters as being parallel to the X, Y, or Z axis.

The address of the circular interpolation parameter for the 4th axis is then equal to that of the associated parallel primary axis.

If an interpolation parameter is not programmed, zero is automatically generated by the control.

Example:

N5 G17 G42 D03 ... LF Plane and tool offset selection


N10 G03 X17 Y30. I-9. J8. LF Complete definition of the  
circle with direction, circle  
end point coordinates and  
interpolation parameters.

N25 G03 X17. I-9. LF Circle programming with  
missing addresses.

If no other plane and traverse distance in the Y axis is programmed between N10 and N25, the control generates the following:

N25 G17 G03 X17. Y30. I-9. J0. LF

3.4.2 Example for circular interpolation using interpolation parameters



Absolute dimension programming

N5 G02 G90 X45. Y30. I0. J15. LF

- The tool moves from point 2 to point 1.

N5 G03 X60. Y15. I15. J0. LF

- The tool moves from point 1 to point 2.

Incremental dimension programming

N10 G02 G91 X-15. Y15. I0. J15. LF

- The tool moves from point 2 to point 1.

N10 G03 X15. Y-15. I15. J0. LF

- The tool moves from point 1 to point 2.

### 3.4.3 Circular interpolation by specifying the radius 1)

The starting point of the circle or arc is determined by the previous block. The end point is given by both of the axis values (e.g. X and Y). The circle centre is defined by the signed radius.


The sign of the radius value is given according to the size of the traversing angle.

less than or equal to	$180^{\circ}$	P+
greater than	$180^{\circ}$	P-

No radii may be programmed, when the distance between the circle end point and circle start point is less than  $10 \mu\text{m}$ , e. a complete circle must be programmed using the interpolation parameters I, J or K.

### 3.4.4 Example of circular interpolation by specifying the radius

The circle centre point is determined by the signed radius.



N5 G03 G90 X60. Y15. P15. LF

The tool moves from point 1 to point 2.

N10 G02 X45. Y30. P15. LF

The tool moves from point 2 to point 1.

1) Only with basic control 4




### 3.4.5 Helical Interpolation 1)

(Requirement: 3D-interpolation) 1)

Helical interpolation is possible between 3 linear axes which are perpendicular to each other. A circle and a straight line are programmed in one block. The straight line is at right angles to the plane with the circular interpolation. The programmed feed rate is maintained along the circular path.

Example: Semicircle with 100 mm radius



The following combinations are possible if the 4th axis was declared a parallel axis to the X-axis:

Straight	Circle	Interpolation parameter
X	Y    Z	J      K
Y	X    Z	I      K
Z	X    Y	I      J
4	Y    Z	J      K
Y	4    Z	I      K
Z	4    Y	I      J

The interpolation parameter of the corresponding parallel axis applies to the 4th axis.

1) with basic controls 3 and 4

### 3.5 G33 Thread Cutting

With boring and milling machines, threads can be cut by using a boring tool or a facing head.

G33 establishes a relationship between main spindle speed and feedrate speed. A pulse encoder generates 1024 pulses for each rotation of the spindle. These are converted by the control and the value defaulted to the feed arrives.

The feed is synchronized with the rotating spindle (i.e. the feedrate need not be programmed). However the feedrate programmed in address F is retained. In order to produce a thread in several passes, the axis will feed when the zero marker pulse initiates the thread cutting cycle. This ensures that the same angle between tool and part is maintained throughout the threading cycle. All threading cuts must be made with the same feed to avoid variations in the following error.

The spindle speed function and the rotation direction should be programmed prior to the thread cutting block proper to allow the spindle to reach the desired speed.

Right-handed and left-handed threads are programmed with M03 and M04 respectively.

The traverse direction depends on the programmed M03/M04.

The programmed thread length should take into consideration the machine axis acceleration and deceleration time; instantaneous acceleration and deceleration is not possible.

The thread length including acceleration and deceleration distance is programmed under the appropriate dimension address. In addition, the tool width must be taken into consideration.

The thread lead is specified under addresses I, J, K.

I, J, K parameters are incremental dimensions.

The dimension value is unsigned. The input resolution for the thread lead is 0.001 mm/rev.

The feed override, feed hold, spindle speed override, and single block switches are disabled when thread cutting.

See Section 8.2.4 for the assignment of thread lead to spindle speed.

#### Thread cutting with different speeds

(Basic control 4B, Option E35)

With this option, no further operator inputs are required. The speed must remain constant during a cut. This function ensures that the same thread part is cut at higher cutting speed as with the lower speed. An offset due to following error no longer occurs.

### 3.5.1 Constant lead tapered threads

For constant lead tapered threads, the thread lead is programmed for the leading axis.

The leading axis is defined as the axis traversing the longest distance.

For equidistant traverse in all axes, the leading axis is defined in the order: X, Y, Z.

The address pairing for thread lead is XI, YJ, ZK.

The 4th axis can take the place of X, Y, or Z. If, for example, the 4th axis is parallel to the Z axis (machine parameter), the 4th axis thread lead is programmed under address K.

#### Example:

G33 X20. Z10. I0.2

Thread lead = 0.2 mm/rev

G33 X10. Z20. I0.2

Incorrect programming

G33 X10. Z20. J0.2

Z is the leading axis


The thread lead must be programmed using K

G33 X10. Z10. I0.2

= 0.2 mm/rev.

G33 X10. Z10. I0.2 K0.2

= 0.2 mm/rev.



} Permissible


G33 Z10. X10. I0.2 K0.2

= 0.2 mm/rev.




## 2.3.2 Feed Direction

Two methods can be used to thread cut. The tool can feed perpendicular to the cutting direction or parallel to the cutting direction.



### "Perpendicular to the cutting direction"

When only one edge of the cutting tool is to cut, both axes must feed. The tool is fed in the direction of cut and perpendicular to the cutting direction before the start of the next threading pass.



### "Cutter Edge Feed"

$$\Delta Z = \Delta X \cdot \tan \frac{\epsilon}{2}$$

### 3.5.3 Variable lead thread

#### 3.5.3.1 Variable lead thread without G34, G35

The thread lead can be modified by programming several contiguous thread cutting blocks. Within a block, the thread lead is constant. The region of constant thread lead can, if desired, be less than a single revolution. Subsequent thread cutting blocks will execute without waiting for the next zero marker pulse of the pulse encoder.

#### 3.5.3.2 Thread cutting G34 (increasing lead) <sup>1)</sup>

The thread lead increases per thread by the value programmed in F up to the maximum possible lead.

N...	G34	G90	Z 17.	K 2.	F 0.1	LF
------	-----	-----	-------	------	-------	----

Initial lead 2 mm  
Lead change +0.1 mm per thread,  
e.g after 5 threads the thread lead is:  
 $2 \text{ mm} + (5 \cdot 0.1 \text{ mm}) = 2.5 \text{ mm}$

#### 3.5.3.3 Thread cutting G35 (decreasing lead) <sup>1)</sup>

The thread lead decreases per thread by the value programmed in F up to the minimum possible lead.

N...	G35	G90	Z 17.	K 200	F 0.5	LF
------	-----	-----	-------	-------	-------	----

Initial lead 200 mm  
Lead change -0.5 mm per thread,  
e.g after 10 threads the thread lead is:  
 $200 \text{ mm} - (10 \cdot 0.5 \text{ mm}) = 195 \text{ mm}$

<sup>1)</sup> Basic control 4B, 4C

Examples for G34/G35 as for G33. Only the thread cutting blocks must be programmed differently if the thread lead is to be increasing or decreasing. The maximum lead modification is 16 mm. It must be programmed without sign. The value should be calculated as follows if the initial and final lead are known:

$$F = \left| \frac{\text{Initial lead}^2 - \text{Final lead}^2}{2 \cdot \text{Thread length}} \right|$$

### 3.5.4 Multiple thread

#### 3.5.4.1 Multiple thread via axial starting point offset

A multiple thread is programmed in the same manner as a single thread. After the first thread is cut, the threading start point is displaced by an amount equal to the pitch circle before the thread cut sequence is repeated.

#### 3.5.4.2 Multiple thread with spindle-specific starting angle offset (Basic control 4B, option E35)


This function makes it possible to cut multiple threads. The spindle-specific starting angle for the respective thread can be programmed via G92 A... . "A" stands for the letter of the angle.

Example: triple thread            1st thread with G92 A0.  
  (0°, 120°, 240°) 2nd thread with G92 A120.  
  3rd thread with G92 A240.

### 3.5.5 Thread Cutting with a Boring Bar

With the workpiece stationary, a thread can be cut by simultaneously rotating and feeding the boring tool. It is necessary to program the bar to retract to the start point:

Before the bar is retracted, the spindle must be stopped in an oriented position (see 4.3). Auxiliary function M19 is executed in the interface control.<sup>1)</sup> The bar is moved out of the cut and with the spindle stopped is retracted to the start position.



1) with basic controls 0, 1 and 2



Example:

Threading a blind hole with a boring bar

Absolute dimension programming

N20	G90	G00	X100.	Y...	S45	M03	LF
N25				Z200.			LF
N30	G33			Z120.	K10.		LF
N35						M19	LF
N40	G00		X105.				LF
N45				Z200.		M00	LF
N50			X100.			M03	LF
N55	G04			F2			LF
N60	G33			Z120.	K10.		LF

Block 20, 25: The boring bar is centred over the drilled hole. The spindle is turned on. Direction M03.

Block 30: The first threading cut is made. The thread end position (e.g. in absolute dimensions) is programmed under address Z. The thread lead is programmed under address K.

Block 35: The spindle is brought to an oriented stop.

Block 40: The boring bar is moved excentrically out of the cut in the X direction.

Block 45: The boring bar is moved out of the hole in the Z direction. It is possible with a programmed stop (M00) to dress the boring bar for a second cut (e.g. manual feed).


Block 50: The boring bar is centered over the drilled hole. At the same time the spindle is turned on.

Block 55: If the positioning time in block 50 is shorter than the time it takes the spindle to accelerate to the correct speed, a dwell time of sufficient length must be programmed in block 55. This ensures that the spindle has reached the desired speed before beginning the next threading pass.

Block 60: A second threading cut begins.

### 3.6 G60 Exact stop (Reset state 10th G group)


With the preparatory function G60 it is possible to position exactly to a target position (within the "exact stop tolerance"). The feed velocity is reduced to zero. The current following error is reduced to zero.



The preparatory function G60 is used, for example, to machine sharp corners, or when reversing direction. Blocks with G00 need not be programmed with G60 as G00 contains exact stop. G60 is modal and is cancelled with G64 (continuous path control) or G63 (tapping with compensation chuck).

The example shows direction reversal with and without G60:

without G60      with G60



### 3.7 G63 Tapping with a floating tap holder

The preparatory function G63 is programmed for tapping drilled holes with a floating holder. The feed axis and spindle rotation are not synchronized.

Spindle speed is programmed under address S with the appropriate feed function programmed under address F. The floating tap must take up length variations resulting from the difference between the tap lead and the lead deviations due to feed rate and spindle speed fluctuations. Sufficient length compensation must be provided on reaching the programmed position to allow for overshoot due to spindle speed run down.

G63 inhibits the feed rate override switch and dependent on the interface design will shut the spindle down when "feed hold" is signalled. The spindle override switch is inhibited.

G63 may only be used with linear interpolation G01. G60 will cancel G63.

### 3.8 G64 Continuous path control

The preparatory function G64 is programmed to assure smooth path transitions between contiguous blocks containing path movements, however, a tangential direction change will result in a rounded corner.

#### 3.8.1 G62 Contour Machining (rounding of block transition by reduced speed)

This function is self-holding like G64. There is deceleration towards the end of the block to the reduced speed input under machine parameter 347. The minimum value of the reduced speed is 5 mm/min.

### 3.9 G04 Dwell Time

The dwell time is programmed under address F.

The dwell time lies between:

1 ms and 99999 ms (F.001 ... F99.999)

A block programmed with G04 may not contain other functions.

e.g.

N.. G04 F11.5 LF

Dwell time 11.5 sec always an unsigned number

When necessary, several contiguous blocks containing dwell functions may be programmed.

Dwell times are programmed when a tool is to cut free of the part and may be used for speed change and machine switching functions. G04 is only valid for the block in which it is programmed.

### 3.10 G70/71 Input Systems

G70 Inch input system

G71 Metric input system

The reset state (basic state) is determined by a machine parameter during commissioning. The control operates internally only with this predetermined inch or metric system, regardless of whether the input is in inches (G70) or metric (G71).

If a value is input to the system, which does not correspond to the basic state, it must be preceded by the associated G-function \*). The control converts the input value into the other system defined in the basic state, so that the converted value is displayed in the system defined in basic state when the block is executed.

A different input system to that defined in the basic state can be programmed for one or more blocks or for a complete program. The required G-function must be programmed in the first block and the reset state must be programmed after the last block (the reset state is automatically selected after M02, M30 program end).

The following are dependent on the reset state of the input system:


- Actual value display (also setpoint/actual value difference)
- Zero shifts
- Feedrate speed G94, G95
- Tool offset

The following are dependent on programmed G70 or G71 functions:

- Path information X, Y, Z
- Interpolation parameters I, J, K
- Chamfers/Radii P-/P
- Parameters, which are not included under path information, interpolation parameters, or chamfers/radii

\*) G70/G71 must be the first function programmed in the block.

Example: G71 = reset state (metric)



SP 00196.0


.  
. .  
. .  
N10 G91 X30. LF  
N11 G03 G70 X1. Y-1. I1. JO. LF  
N12 G01 G71 Y-20. LF  
. .  
. .  
. .

### 3.11 Zero offsets (ZO)

$$ZO = \text{set. ZO (G54-57)} + \text{add. ZO (G59)} + \text{ext. suppl. ZO}$$

The zero offset is the difference between the workpiece zero (to which the measurements are related) and the machine zero.

Zero offset using one axis / and a selected group\* as an example:



\*) Basic control 4B, 4C

\*\*) Can be selected via machine datum

### 3.11.1 G54/G55/G56/G57 Settable Zero Offset

(G54 is the reset state of the eighth G group)

Values for the zero offset for each axis can be entered into the control via the operator panel.

The offset is included when calculating the block end point in absolute and incremental data blocks, when the associated axis is programmed

with incremental data blocks (G91) any change in zero offset is taken into account.

#### Example:

Change from G54 to G55 in an incremental data block. The resulting difference between Z0 (G55) and Z0 (G54) is included in the calculation (see block increment calculation, section 8.2.3).

Four or twelve\* settable zero offsets per axis can be selected.

An external supplementary zero offset (ext. add. zero offset) originating in the interface control is added to the value selected by G54 and the programmed Z0. The result is equal to the total zero offset.

\* Basic control 4B, 4C



Selection of settable zero offset

(from basic version 4B, 4C)

The settable zero offset (Z01-Z012) is selected by G54 to G59 and additional interface signals for groups 1 to 3.

	Group 1	Group 2	Group 3
G54	Z01	Z05	Z09
G55	Z02	Z06	Z010
G56	Z03	Z07	Z011
G57	Z04	Z08	Z012


Release of the interface signals for instance via M-function. For reasons of clarity, L99 "Delete buffer store" must be programmed and the cutter radius compensation cancelled.

Example:

```
N10 G40 X..... LF
N15 M.. ..... LF Selection of zero offset groups
                        1 to 3 using an M function
N20 L99 ..... LF Delete buffer store (see section 5.6.)
N25 G56 ..... LF Selection of zero offset
```

### 3.11.2 G59 Programmable Zero Offset

An additional zero offset can be programmed with G59 under addresses X, Y, Z or 4th axis (if main axis). The programmed value is added to the settable zero offset and the external suppl. offset.



#### Settable Zero Offset:

Input Value:  $XMW_1 = 0$   
 $ZMW_1 = 500$

#### Programmed Additive Zero Offset:

Input Value:  $XMW_2 = 600$   
 $ZMW_2 = 600$

#### Resultant Zero Offset:


$XMW = 600$   
 $ZMW = 1100$

Example:

The contour is programmed in absolute dimensions. To allow for finishing stock, the entire contour can be displaced in Y with a programmable (additive) zero offset.

Selected with N.. G59 Y ... LF (Value input)

Cancelled with N.. G59 Y0. LF (Value deleted)



Programmable additive  
zero offset in Y

With M02/M30 (program end) or on program abortion, the programmable zero offset is automatically cleared since a new program start will reload the offset value.

### 3.11.3 G53 Cancelling the zero offsets

G53 suppresses blockwise the coordinate displacement achieved by

- settable ZO (G54 - G57)
- programmable additive ZO (G59)
- external additive ZO

The tool offset must be separately cancelled.

In the block following G53 all zero offsets are again active.

Example: referred to machine zero point

N1232	G40	X...	Y...	LF	- cancellation of tool offset
N1233	D00	Z...		LF	- cancellation of length compensation
N1234	G53	X...	Y...	LF	- cancellation of all ZOs

### 3.12 G94/G95 Feed F

The programmed feedrate when using cutter radius compensation is maintained on the contour surface.

- G94 feedrate F in mm/min
- G95 feedrate F in mm/rev.

For the relationship between the rotational feedrate and the spindle speed, see section 8.2.4.

With rotary axes, the feed function is programmed under address F as an angular velocity in degrees/minute. The feed can be programmed in feed/minute instead of degrees/minute, however, the angular velocity and the part radius must be used to calculate circumferential velocity.

For the unit circle diameter

$$D_0 = 1 \text{ mm} \times \frac{360}{\pi} = 114.592 \text{ mm}$$

The resultant vectorial tangential velocity at  $1^\circ/\text{min}$  equals 1 mm/min.

If a rotating axis is only moving and the stationary tool tip contacts the part surface at a diameter equal to D, then the surface velocity of the tool tip relative to the part surface equals:



$$V_{\text{tool}} \text{ (mm/min)} = \frac{D}{D_0} \times V_{\text{programmed}} \text{ (deg./min)}$$

$$V_{\text{programmed}} \text{ (deg./min)} = \frac{D_0}{D} \times V_{\text{tool}} \text{ (mm/min)}$$

The feedrate override switch located on the operator panel can modify the programmed feed from 1% to 120%. The 100% setting corresponds to the programmed value.

# Velocity Transitions

N95	G91	G42	G00	X10.					LF
N100			G01	X10.	F200				LF
N105				X10.	F300				LF
N110				X10.	F200				LF
N115				X20.	Y20.				LF
N120			G02	X ...	Y ...	I ...	J ...		LF
N125			G01	X ...	Y ...				LF




In block N120 the feedrate changes with respect to the cutter centre path in relation to the two radii (cutter radius, contour radius).

1) Speed transition can be selected as a ramp or jump function (machine data)

The following holds true when simultaneously moving a linear and rotary axis:

Whenever the distance between the tool tip contact point and rotary axis remains constant, the speed of the tool at the workpiece will also be constant. A constant path velocity also results when linearly interpolating a rotary and linear axis in a path parallel to the axis of rotation (helical cutting on a cylinder). The resultant path velocity of the tool tip relative to the cylinder surface is a function of the programmed velocity, the cylinder diameter and the slope of the helix.



$$V_{\text{tool}} = V_{\text{programmed}} \sqrt{1 + \frac{D^2 - D_0^2}{D_0^2} \cos^2 \alpha}$$


- $V_{\text{programmed}}$  = programmed path velocity in deg./min
- $D$  = helix diameter in mm
- $D_0$  = unit circle diameter = 114.592 mm
- $\alpha$  = arc tan  $\frac{Z}{C}$  (slope angle of the helix with  $D = I$ )
- $Z$  = programmed departure (mm)
- $C$  = programmed angle in degrees
- $\alpha'$  = arc tan  $\frac{Z}{C \times \frac{D}{D_0}}$  (slope angle of the helix with  $D \neq D_0$ ).

If the distance between tool tip, work surface and the rotary axis is not held constant (e.g. spiral in a plane), the path velocity will not be constant. The path velocity will continually change as a function of the variable machining diameter.

A constant path velocity can be simulated by splitting the programmed block into several contiguous blocks in which the feed function is changed to approximately the desired velocity. A subroutine program using parameter chaining is a useful technique for velocity approximation.



### 3.13 G17, G18, G19 Machining plane selection



By programming G17 - G19, the plane is defined in which cutter radius compensation is available. If a plane has not been selected at the start of the program, the default plane will be defined by G17 (default setting of the 4th G group).

With a 4th axis the cutter radius compensation plane is defined as follows:

G code \ 4th axis	parallel to X	parallel to Y	parallel to Z	machine without a 4th axis
G17	X-Y *4-Y	X-Y *X-4	X-Y	X-Y
G18	Z-X *Z-4	Z-X	Z-X *4-X	Z-X
G19	Y-Z	Y-Z *4-Z	Y-Z *Y-4	Y-Z

(4th axis - see Section 2.1)

\*) 4th axis equals main axis

### 3.14 Tool Offset

Two geometric values are stored under a tool offset number:

1st length  $\pm$  999.999 mm  
2nd length  $\pm$  999.999 mm (radius)

A total of 64 offset pairs are available.

A tool offset is called via the 2 digit designator D01 ... D64. 1)

- Tool offset input via tape

```
%TO          LF (TOOL OFFSET)
G92 D01 D... P... LF
G92 D64 D... P... LF
M02 or M30    LF
```

The tool length is stored under D..., the radius under P... .

#### Selecting and cancelling the length compensation

The selection is only possible, when G00 or G01 are active.

The plane perpendicular to the plane in which the compensation should act must be selected.

```
N5 G00 G17 D... Z...
```

Only the length compensation is used from the store D... .

The compensation value contained in the D word is always used in the calculation with its sign according to the programmed axis.

The length compensation is cancelled via D00.

The compensation is only executed when the respective axis is programmed.

- 1) Basic controls 0, 1, 2, 3  
max. 32 tool offset pairs (D01...D32)

1. Length compensation without CRC

N5 G90 G00 G17 D01 Z... Selection of the length  
compensation (e.g. boring tool)

N50 D00 Z... Cancellation of the length  
compensation via D00

2. Length compensation with CRC (3.15)

N5 G90 G00 G17 G41 D02 X... Y... Automatic selection of  
N10 Z... the CRC with length  
compensation

N50 G40 X... Cancellation of the CRC  
only. The length  
compensation is not  
cancelled.

N51 D00 Z... Cancellation of the  
length compensation.

3.15 G40/G41/G42 Intersectional Cutter Radius Compensation  
(Option)

- G40 Cutter compensation off
- G41 Tool left of the part - in traverse direction -
- G42 Tool right of the part - in traverse direction -

The cutter radius compensation is active in the selected plane (G17 to G19). The length compensation of the cutter is always active perpendicular to the selected plane, in this case to the third axis.

When mirror imaging is used and the sign is considered, the traversed path is as follows:

Both axes are mirrored or Neither axis is mirrored		one axis is mirrored		
Sign for the radius compensation value of the cutter				
G41	+ left	- right	+ right	- left
G41	right	left	left	right

Selecting and cancelling the intersectional cutter radius compensation.

The selection is only possible when G00 or G01 is programmed. G40, G41, and G42 may be programmed in a block without axis motion. However, at least one axis motion must be programmed in order for them to become active. In the selection block only the axes of the selected plane may be programmed.

Example for the selection

N10 G01 G17 G41 D07 X... Y... LF - When the end position of this block is reached, the path in the selected plane is correctly compensated. Only the radius is compensated.

N15 Z... LF - The length compensation is activated.

or

N10 G17 LF - Plane selection

N15 G41 D07 LF - Compensation selection

N20 G01 X... Y... LF - When the end position of this block is reached, the path in the selected plane is correctly compensated. Only the radius is compensated.

N25 Z... LF - The length compensation is activated.

With G40 the compensation (G41 or G42) is cancelled. At least one axis motion must be programmed in the selected plane in order to restore the tool to its uncompensated path. The length compensation is cancelled by D00. The uncompensated path is obtained when the axis parallel to the length compensation is programmed.

Example for the cancellation:

N30 G40 X... LF - Cancellation of the radius compensation

N35 D00 Z... LF - The length compensation is cancelled.

r:  
N30 G41 D00 X... LF - Cancellation of the radius compensation via D00.

N35 Z... LF - The length compensation is cancelled.

Change from G41 to G42

N10 G01 G17 G41 D12 X... Y... LF - Radius compensation  
N15 Z... LF - Length compensation  
N20 G42 X... Y... LF - Change in the radius compensation (e.g. change in direction relative to the workpiece; straight milling)  
N25 Z... LF - No change in the length compensation.


## Change in the tool offset function

The G function does not have to be reprogrammed.

```
N10 G01 G17 G41 D12 X... Y... LF
N15           Z...           LF
N20           D10 Z...       LF - Change in the length compensation
N25           X... Y...     LF - Change in the length compensation
```

With radius compensation selected, G92, G59, and G33 must not be programmed. Remedy: Program the functions (G92, G59, G33) before selecting radius compensation, or switch off the radius compensation, select G92, G59 and G33, and then again select radius compensation. With radius compensation selected (including G40 block) the effective zero offset value may not be changed.

Example: Milling with CRC




N1	G01	G41	D01	G90	G17	X30.	Y90.	F5000	S56	M03	LF
N2	G91					X30.	Y30.				LF
N3	G02					X30.	Y-30.	I0.	J-30.		LF
N4	G01					X30.					LF
N5	G02					X30.	Y30.	I30.	J0.		LF
N6	G01					X-15.	Y-30.				LF
N7						X+15.	Y-30.				LF
N8						X-30.					LF
N9						X-30.	Y-30.				LF
N10						X-45.	Y30.				LF
N11						X-15.	Y30.				LF
N12	G40	G90				X0.	Y90.				LF
N13	...										

The cutter used has a radius of 14.000 mm. The radius dimension is stored under address D01.



Example: Full circle programming with CRC



----- Cutter Centre Path  
 \_\_\_\_\_ Part Contour

N1	G90	G00	G17	G41	D01	X80.	Y30.		LF
N2	G03					X130.	Y80.	I0. J50.	LF
N3	G91	G02				X0.	Y0.	I50. J0.	LF
N4	G90	G03				X80.	Y130.	I-50. J0.	LF
N5	G00	G40				X70.	Y80.		LF

### 3.16 G43/G44 Tool Length Offset (positive, negative) 1)

G43 Positive tool length offset (reset state)

G44 Negative tool length offset

When selecting the tool length offset G43 is active, if G44 has not been previously programmed. The tool length offset is active in the axis perpendicular to the CRC-plane.

The tool length offset is cancelled with D00. The uncompensated path is traversed when the respective axis is programmed (s. Sections 3.14 and 3.15).

1) with basic control 4

## Sign Convention

A plus sign is input by the operator, when the actual dimension of the tool is greater than the programmed value. A minus sign is input, when the actual dimension of the tool is smaller than the programmed value.

For example:

The actual drill length is longer than  
the programmed drill length + offset

---


The actual drill length is smaller than  
the programmed radius - offset

### G43 positive tool length offset

The offset called by the D word is calculated with its sign to the associated axis.

### G44 negative tool length offset

The offset called by the D word is calculated with its opposite sign to the associated axis.



### 3.17 Milling of cylindrical contours G92 P 1)

(Prerequisite: Option B61)

With cylindrical interpolation it is possible to machine cylindrical contours by coordinating the motion of a rotary axis with a linear axis while the rotary axis diameter is held constant. Straight contour paths as well as arc contour paths using intersectional cutter compensation can be programmed.

The rotary axis angle is dimensioned in degrees:

The circumferential dimension is calculated by the control.

The diameter is defined as

$$P = \frac{\text{part contour diameter}}{\text{unit circle diameter}}$$

and programmed with G92 P. This ratio can range between 0.00001 and 999.99999.

Input system	Unit circle diameter
metric	114.592 mm
inch ( $10^{-4}$ )	11.4592 inch

The unit circle diameter is derived from the relation

$$\pi \times d = 60.$$

$$\text{Unit circle diameter} = \frac{360}{\pi} \text{ in mm or inch}$$


Apart from the names of the axes, no other signs may be written in a block with G92 P.. .

1) with basic control 4

N.. G92 P... C LF


Factor for normalized  
circle  
part contour diameter  
unit circle diameter

Rotary axis (e.g. C)  
associated with the  
normalized circle



- The factor for the normalized circle is modal but can be redefined in subsequent blocks. The value is reset with M02/M30.
- The programmed feedrate is maintained on the centre path.
- As long as the factor is  $\neq 1$ , this axis (e.g. C) can only interpolate with one other axis; i.e. interpolation with more than 2 axes is possible only after the factor is set to 1.
- Cutter radius compensation cannot be used with cylindrical interpolation!

Example:



N10 G92 P3 B

LF - Select cylindrical interpolation

N11 G01 B40.

LF

N12 G03 B60. Y216. P+60.

LF

N13 G01 B100. Y456.

LF

N14 G02 B150. Y549. P+165.

LF

N15 G01 B260.

LF

N30 G92 P1. B

LF - Delete cylindrical interpolation

- 4th axis (B) parallel to X-axis


- 4th axis (B) = main axis

### 3.18 G10/G11 polar coordinate programming

1)

G10 Linear interpolation rapid traverse

G11 Linear interpolation feedrate (F)




W = Workpiece zero

P1 = Centre point in the polar coordinate system

A = Angle

P = Radius

Example traverse from P1 to P2.




- The angle always refers to the positive axis programmed first (in this case X-axis). The positive direction of the first programmed axis is equal to an angle of 0 degrees. The positive direction of the second axis programmed is equal to an angle of 90 degrees.
- The angle value is always absolute and positive. Input resolution  $10^{-5}$  degrees.

1) with basic control 4

- When first programming the polar coordinates, both centre point coordinates must be programmed in absolute dimensions. It is recommended to program both centre point coordinates.
- The centre point is modal and can be reprogrammed. On "End of Program" (M02/M30), the centre point dimension is cleared.
- The incremental programming of the centre point (with G91) is always referenced to the previously programmed centre point.

### Application

E.g. for multiple hole drilling where all hole dimensions are with respect to a common centre point.



The angles are with reference to the X-axis since the centre point coordinate in X is programmed first.

### Programming:

```

N10 G90 G10 G81 X... Y... A... P(r1) R01... R02... R11... LF
N15      G10      A... P(r2) LF
N20      G10      A... P(r3) LF
N25      G10      A... P(r4) LF
N30      G80      LF
A... P(r.) = Hole position in polar coordinates
X... Y...  = Centre point of the polar coordinate system
G81        = Drilling cycle selection
G80        = Drilling cycle cancellation

```





- Program execution:
- approach drilling location B1
  - perform the desired cycle
  - approach drilling location B2
  - perform the desired cycle
  - etc.
  - G10 must be programmed in each block as G81 terminates with rapid traverse

Application

E.g. Milling of a hexagon head

e.g. Approaching drilling positions



N11	F1000	LF	N11	G81	F1000	LF				
N12	G90	G11	X50.Y35.P20.A	0.LF	(P1)	N12	G90	G10	X50.Y35.P20.A	0.LF
N13		A	60.LF	(P2)	N13	G10		A	60.LF	
N14		A	120.LF	(P3)	N14	G10		A	120.LF	
N15		A	180.LF	(P4)	N15	G10		A	180.LF	
N16		A	240.LF	(P5)	N16	G10		A	240.LF	
N17		A	300.LF	(P6)	N17	G10		A	300.LF	
N18		A	0.LF	(P1)	N18	G80			LF	

P... A... = Position in the polar coordinate system  
 X... Y... = Centre point in the polar coordinate system  
 G81 = Drilling cycle selection  
 G80 = Drilling cycle cancellation

### 3.19 G36/G37, "TRANSMIT" coordinate transformation (Option B65)

Milling of rotary parts on rotating tables whereby the desired contour is achieved by interpolation of the rotary axis with a linear axis (application with special machines). The TRANSMIT function permits contour programming in a "fictitious" Cartesian coordinate system while the machine moves in a real polar coordinate system.

The fictitious Cartesian coordinate system is formed by the 1st X axis and the 4th axis (rotary axis).

The rotary axis is then labelled with the address "C" and the fictitious axis with the symbolic address "Cf".

The transformation is selected and cancelled in the program using G-functions.

#### G36 coordinate transformation cancelled (reset position)

Programming is as normal in the real Cartesian system (machine coordinate system).

Rotary axis C in degrees, speed in degrees/min.

#### G37 TRANSMIT coordinate transformation selected

Programming is in the fictitious cartesian coordinate system.

For further information see also SINUMERIK 3T/3TT programming guide.

- With G17/18/19 the missing axis of the current fictitious plane is provided when only one axis in the block is programmed and this axis is an axis of the selected plane (example a and b).
- If only one axis of the fictitious plane and one axis which does not belong to the fictitious plane is programmed, the controller outputs Alarm 504 (example c).
- Both axes of the fictitious plane must be programmed if other axes in addition to the axes of the plane are programmed in this block (example d).

Example: G37 active, X - Cf = fictitious plane = G 17 - plane

- a) G17 X.. LF = Cf is provided
- b) G17 Cf.. LF = X is provided
- c) G17 X.. Z.. LF = Alarm 504
- d) G17 X.. Cf.. Z.. LF.. = no axis provided  
no Alarm
- e) G17 Z.. LF = - " -


- The cutter centre must be on the X axis in the centre of rotation.
- The controller cannot compensate for an offset in the direction of Cf.
- The workpiece zero is in the rotary axis centre.
- If the cutter radius path correction (G41/42) is selected the transformation must neither be switched on or off (changeover from G36/G37).
- Within a sequence of contour definition blocks the transformation must not be switched on or off (changeover from G36/G37).
- Rapid traverse movements are to be programmed with the appropriate F value under G01 or G11.
- When changing from G36 to G37 the actual value of the C axis is set to the value 0 and the actual value of the X axis to the machine actual value regardless of any offsets to be carried out (Z0). Zero offsets are calculated according to the Cartesian system.

The external zero offsets for the C-axis must be zero for G37 in the inch input system, as the position of the decimal point is different.

The tool path feed rate is programmed in the X Cf coordinate system where it is constantly retained. In G37 the tool path feed rate is monitored to prevent the maximum permissible C axis speed from being exceeded.

- The precision which can be achieved on the part when the C axis is used depends on the current working radius (control in degrees).
- A block search via G37 blocks is not permitted.
- If automatic mode is interrupted, the system programmed with G36/G37 is retained. Traversing is thus possible in the Cartesian system in job mode.

Programming example: Cutting a "transverse contour" with TRANSMIT



```

-%1234
  X.. C.. Z..
  *
  *
N50 X.. C.. Z..
N55 G0 x 120 C0 Z100 D50
N60 G37 G01 F200 Z90
N65 G42 X90 C0
N70 X40 C40
N75 X-60
N80 G02 C-40 J-40
N85 G01 X40
N90 X90 C0
N95 G40 X120
N100 Z100
N105 G36
N110 X.. C.. Z..
  *
  *

```

Real coordinate system

Approach starting point  
Select length correction

Activate transformation module with G37.

Program in fictitious coordinate system

Selection of cutter radius correction (C corresponds to fictitious axis C<sub>f</sub>)

Semi-circle

Cancellation of cutter radius compensation


Retraction in Z

Deactivate transformation

Real coordinate system

### 3.20 Programmable coordinate rotation <sup>1)</sup>


Programmable turning of coordinates permits a part program or section of a part program to be rotated by a certain angle. The rotation point is the sum of all zero offsets.



- The rotation angle must not be negative or greater than 360 °.
- The rotation angle can also be programmed by chaining R parameters.
- The rotation angle is automatically deleted at the end of the program.
- The level can only be changed when the rotation angle is 0.
- The rotation angle is only displayed with G59.
- The main axes in the level selected can be rotated.

1) Option only basic control 4B, 4C


- After a G59 block with rotation angle, both axes to be rotated must be traversed to give the NC a new reference point.
- In the 3 M system, rotation can change a 2 D block to a 3 D block. If the 3 D interpolation option is not available, an alarm is output.
- When an axis is mirrored, the block to be traversed is first rotated and then mirrored.
- In a G53 block, coordinate rotation is not effective.
- If a G37 (Transmit) is programmed while coordinate rotation is active, both axes must be traversed in the next block.
- Rotation angle direction in plane selected.



- If the rotation angle is written via @ 29, a @ 31 block must be programmed before @ 29, so that the rotation angle is effective from the next block.



Example:



M = Machine zero

W1 = Workpiece zero of % 1 (without programmable coordinate rotation)

W2 = Workpiece zero of % 2 (with programmable coordinate rotation)

% 1  
⋮  
⋮

% 2  
⋮  
⋮

N5	G54	LF		N5	G54	LF				
N10	G59	X0	Y0	LF	N10	G59	X25	Y30	A50	LF Selection of coordinate rotation
N15	G00	X0	Y0	LF	N15	G00	X0	Y0	LF	
N20	G01	X20	LF		N20	G01	X20	LF		
N25	G03	Y10	O5	LF	N25	G03	Y10	P5	LF	
N30	G01	X0			N30	G01	Y0			
N35	G01	Y0			N35	G01	Y0			
N40	M30	LF			N40	G59	A0	LF		Deselection of coordinate rotation

### 3.21 Dynamic smoothing exponent for threads

This influences the run-up time of feed drives for threads as machine data 120 - 123 (acceleration) are ineffective when G33 is selected. The number of spindle actual value pulses for the speed of the feed axis are smoothed.

The smoothing and runup time is programmed as a dedicated block.

N.. G92 T. LF

The value is written into machine data item 358. The exponent can have the value 0 to 5. The value can also be programmed with R parameters.

Programmed value						
G92 T..	0	1	2	3	4	5
Cycle time times	0	1	3	7	15	31

Use the actual value scanning cycle time as time-base.

#### 4. Miscellaneous and auxiliary functions S, T, M, H

The miscellaneous and auxiliary functions are output when the program block in which they are programmed is executed. A maximum of one M, one S, one T and one H function may be programmed in one block. The functions are output to the interface control in the following sequence:

- M
- S
- T
- H

A machine parameter is used to define whether the function is output before or while the programmed axis is in motion. See the machine tool maker's data.

If the functions are output while the axis is in motion, the following will hold true:

If a new function is to be in effect before an axis is traversed, the function must be programmed in the preceding block.


##### 4.1 S Word

The S-function may be selected to specify:

- Spindle speed as a coded number
- Spindle speed in rpm. or 0.1 rpm  
(defined by machine parameter)

## 4.2 Tool function T

The tool function designates the tool necessary for a machining operation.



## 4.3 Miscellaneous function M

### M00 Programmed stop (unconditional)

M00 is used to stop an executing program to enable an operation e.g. a measurement, to be performed and when completed, program execution can recommence by pressing the "cycle start" key. Stored information is not affected. The miscellaneous function M00 functions in all automatic modes. Whether or not the spindle is stopped depends on the machine tool and is specified in the machine Programming Instructions.

M00 is effective in blocks programmed with or without path information. "M0" is recognized as an M00.

### M02 End of program

M02 with reset to the first program block is programmed in the last program block. M02 may be programmed alone or together with other functions in a block.

The read-in procedure is stopped with M02.

M2 is recognized as an M02.

The control will revert to its default state (see program key).

1) with basic control 0

## M17 End of subroutine

M17 may be programmed alone or together with other functions in the last subroutine block. M17 only signals the end of a subroutine. A subroutine call and M17 (e.g. with nesting) may not be programmed in the same block.

## M30 Program end

M30 is similar to M02; automatic tape rewind is not possible. This can only be carried out by operating the tape reader manually.

## M03, M04, M05<sup>2)</sup> Main Spindle Control

(M19 only in conjunction with encoder on main spindle)

The following M words are defined for analog spindle control with analog spindle speed output:

M03 Spindle rotation clockwise  
M04 Spindle rotation counter-clockwise  
M05 Spindle stop  
M19 Oriented spindle stop<sup>2)</sup>

It is possible to stop the main spindle with orientation using M19 S. The angle can be programmed under address S in degrees (distance to the zero mark in M03 direction). The programmed angle under address S is retentive. When M19 is programmed without S, the stored value for the angle is active. M19 does not deselect M03 or M04.

Programming M19 S123 LF, whereby S can be omitted.

## Unassigned additional functions

All additional functions except for M00, M02, M03, M04, M05, M17, M19, M30 are available for use.

2) with basic controls 3, 4

Exact information about the use of the individual functions is given in the respective program key of the particular machine. These functions are defined partially in DIN 66025.

#### 4.4 Auxiliary Function H 1)

The address H is available for switching functions or motions not controlled by the NC. One auxiliary function is available per block, which can be used for programming a maximum of 4 decades. Please refer to the Programming Instructions of the machine tool maker for further details.

#### 4.5 Rapid switching and auxiliary functions 2)

When programming M 12, H 1234, block processing in automatic operation is speeded up as the system does not wait for PLC acknowledgement. All functions are output rapidly with S and T functions (can be selected via machine datum). In the last block of a main program no rapid auxiliary functions may be programmed.

- 1) with basic control 4
- 2) with basic control 4C

## 5. R Parameters

Part programs may be programmed with parameters instead of numerical values for the dimension data. Parameters R00 - R99 <sup>1)</sup> can be assigned to all addresses except N.

A parameter is set equal to a numerical value in the part program or in the subroutine. R parameters must always be programmed as a 2-digit number. A maximum of 10 parameters are allowed in a block.

From basic control 4C on, a total of 500 R parameters are available. They are divided into 5 groups of 100 R parameters each in groups 0 to 4. The parameters can be addressed within each group via addresses R00 to R99. The groups can be selected via the function @28x (x = 0 to 4, depending on the group). The following examples and sections 5.1 to 5.5 are valid for one R parameter group in basic version 4C.

Note: When using cycles (L95 to L903) only R parameters R00 to R49 are freely available. The R parameters from R50 onwards are used for cycle calculation.

### Example:

```
L5100                                     Parameters R01, R05, and R29
N1   X-R05   YR01   LF                    are used in subroutine.
N2   ZR29                                     LF
N3   XR05   Y-R01   LF
.
N50  M17                                     LF
%    4081                                     LF
N1   . . . .                               LF
.
N37  R01    10.  R29-20.05  R05  500.  LF  Value assignments
N38  L5102  LF
```

Subroutine L51 is called, it will run twice

```
R01   =   10.
R05   =   500.
R29   =  -20.05
```

1) with basic controls 0, 1, 2: 50 parameters R00 to R49

## 5.1 Parameter definition

With parameter definition, individual R parameters are assigned to signed numerical values. The R parameters are assigned in part programs or subroutines. Up to 10 parameter definitions may be programmed in one block.

Programmed operation	Execution	Result
R01 10.78	R01 +10.78	R01 = +10.78
R02 95.34	R02 +95.34	R02 = +95.34
R03 -555.1	R03 -555.1	R03 = -555.1

## 5.2 Assigning parameters in a program

Direct assignment for dimension data only. An address is given the value defined by the R parameter.

Programmed operation	Execution	Result
XR01	XR01	X = +10.78
ZR	ZR03	Z = -555.1
X-R03	X-R03	X = +555.1

### Arithmetic assignment

To the numerical value of an address, the control performs a signed addition or subtraction with the parameter value.

Programmed operation	Execution	Result
X 20.78 - R01	X = (20.78 - 10.78)	X = 10
Z 44.9 - R03	Z = 44.9 - (-555.1)	Z = 600
X 10.1 R02	X = + 10.1 +95.34	X = 105.44

The sequence address, numerical value, parameter must be maintained.

An unsigned parameter or number is assumed positive.



### 5.3 Operations with parameters

Arithmetic function	Programmed operation	Execution	Result is stored in
Addition	R01 R02	R01 + R02	R01
Subtraction	R01 - R02	R01 - R02	R01
Multiplication	R01 · R02	R01 · R02	R01
Division	R01/R02	R01 : R02	R01
Parameter Definition and Addition	R01 10 R02	R01 = 10 R01 + R02	R01
Parameter Definition and Subtraction	R01 -10 - R02	R01 = -10 R01 - R02	R01
Square root 1) Sine 1) Arctan 1)	@ 10R01 @ 15R01 @ 18R01	$\sqrt{R01}$ sinR01 arctan (R01:R02)	R01 R01 R01

The @ symbol is produced by pressing the  $\frac{7}{\%}$  key and then the  $\frac{\cdot}{R}$  key.

1) Basic controls 3 and 4

Only R parameters may be multiplied or divided with one another; i.e. a parameter and a number may not be multiplied or divided together. The decimal point defines the operation as multiplication. The block skip character "/" defines the operation as division.

The sequence determines the order in which the expression is evaluated. @10, @15, @18 must be programmed in one block.

The control calculating time is app. 10 msec per operation. Only one operation per block may be programmed.

Range:           smallest value:  $1 \cdot 10^{-8}$   
                  largest value:  $2^{27} - 1$

Display:       floating decimal point ( $\pm .8$ ) to ( $\pm 8.$ )   1)


1) Basic controls 0, 1, 2 ( $\pm .7$ ) to ( $\pm 7.$ )

## 5.4 Parameter chaining

Through parameter chaining a parameter value is altered continually as it loops through a section of program or a subroutine. A calculation is performed whenever chaining parameters are encountered in a running program.

The last parameter of the chain remains unchanged.

A maximum of 4 parameters may be chained.



### Conventions for evaluating an expression

A new R parameter is calculated from the chaining of two parameters and the sign between them. The parameter value is sign-dependent (i.e. it can be positive or negative).

### An example of chaining 2 parameters

R01 + R02	R01 <sub>new</sub>	=	R01 + R02
-R01 + R02	R01 <sub>new</sub>	=	R01 + R02
R01 - R02	R01 <sub>new</sub>	=	R01 - R02
-R01 - R02	R01 <sub>new</sub>	=	R01 - R02
R01 · R02	R01 <sub>new</sub>	=	R01 · R02
R01 / R02	R01 <sub>new</sub>	=	R01 / R02

### An example of chaining 4 parameters

-R01 + R02 · R03 - R04	R01 <sub>new</sub>	=	R01 + R02	3
	R02 <sub>new</sub>	=	R02 · R03	6
	R03 <sub>new</sub>	=	R03 - R04	-1
	R04 <sub>new</sub>	=	R04	

The parameters as well as the parameter value may be a signed number.

Example:

<pre>%9534LF N1 L0105 R01-10. R02 81. R03 3. LF N6 L0204 R04-1. R05 2. R06 4. LF N100 M30 LF</pre>	<p>A subroutine call to loop 5 times and 4 times resp. Parameters are defined prior to subroutine entry as:  R01 = -10. R02 = 81. R03 = 3.  R04 = -1. R05 = 2. R06 = 4.  R07 = -1.</p>
<pre>L0100 (3-parameter chaining) N5 X1000. -R01 +R02/R03 LF N10 M17 LF</pre>	
<pre>L0200 (4-parameter chaining) N17 Y500. +R04. R05 +R06 +R07 LF N20 M17 LF</pre>	

The following numerical values are taken by the motion axes and the parameters.

L0100		X	-	R01	+	R02	/	R03
Pass	Definition	1000.		-10.		81.		3.
1	value ass.	1010.		71		27.		3.
2	value ass.	929.		98.		9.		3.
3	value ass.	902.		107.		3.		3.
4	value ass.	893.		110.		1.		3.
5	value ass.	890.		111.		0.333		3.

L0200		Y	+	R04	·	R05	+	R06	+	R07
Pass	Definition	500.		-1.		2.		7.		-1
1	value ass.	499.		-2.		6.		3.		-1.
2	value ass.	498.		-12.		9.		2.		-1.
3	value ass.	488.		-108.		11.		1.		-1.
4	value ass.	392.		-1188.		12.		0.		-1.

At the end of a program, the parameters take on the values assigned to them in the last performed parameter manipulation. This value remains stored until the parameter is redefined or a parameter manipulation is done resulting in a new value.

## 5.5 Programming examples using parameters

### Example: a rectangle

The following subroutine illustrates the machining of a rectangle in the X, Y plane whose sides vary dimensionally. The rectangle sides are assumed parallel to the machine axes.

#### Subroutine


```

L4600
N5   G01  G64  G91  Z-R02          LF
N10          X R00                LF
N15  G02          X R03  Y-R03  I0  J-R03  LF
N20  G01          Y-R01          LF
N25  G02          X-R03  Y-R03  I-R03  J0  LF
N30  G01          X-R00          LF
N35  G02          X-R03  Y R03  I0  J R03  LF
N40  G01          Y R01          LF
N45  G02          X R03  Y R03  I R03  J0  LF
N50  G01          Z R03          LF
N55  M17                                LF
    
```

#### Subroutine call:

```


N26  G90  X . . . Y . . .          LF  1st subroutine
N27  L46  R00 60  R01 30.  R02 5  R03 3  LF  entry
N28  G90  X . . . Y . . .          LF  2nd subroutine
N29  L46  R00 40.                  LF  entry
    
```



R02 = Dressing depth in the Z axis direction  
P1 = Start and end point of the subroutine

Example: Machine an internal semi-circle surface

The following subroutine illustrates a stock removal and finishing operation for a semi-circle. The contour radius and the cutter entry radius are written as parameter variables. Each time the subroutine is run, the actual part dimension can be compared to the programmed dimension. The resulting difference is stored as a additive tool wear offset.



Subroutine:


L0100	
N1 R01-R09	LF Calculate cutter entry radius
N2 G00 G64 G91 G17 G41 D01	LF Position to cutter entry point
X-R01 YR09	LF
N3 R01+R09	LF Reset R01 to original value
N4 G03 X-R09 Y-R09 I0. J-R09	LF Position to contour
N5 XR01 Y-R01 IR01 JO.	LF Machining
N6 XR01 YR01 I0. JR01	LF Machining
N7 X-R09 YR09 I-R09 JO.	LF Position from contour
N8 R01-R09	LF Calculate workpiece centre
N9 G00 G40 X-R01 Y-R09	LF Positioning
N10 R01+R09 M01	LF Reset R01 to original value
N11 M17	LF End of subroutine

Subroutine call:

% 5873	LF
N1 ...	LF
N2 L0101 R01 50. R09 10.	LF
N3 ...	
.	
.	

## Example: Straight Milling

The path transitions are programmed with radii to avoid a reduction in the feed rate. In this manner dwell marks are avoided during a path direction change.



### L34 is called by another program:

N15 L3409 R00 40. R01 10. R02 480. F200 LF

### Subroutine:

```
L3400
N1 G01 G64 G91 XR00 LF
N2 G03 XR01 YR01 IO JR01 LF
N3 G01 YR02 LF
N4 G02 XR01 YR01 IR01 JO LF
N5 G01 XR00 LF
N6 G02 XR01 Y-R01 IO J-R01 LF
N7 G01 Y-R02 LF
N8 G03 XR01 Y-R01 IR01 JO LF
N9 M17 LF
```

## 5.6 Empty buffer store, L99; @ 31

A series of control signals from the interface control (parallel interface or PLC) are registered in the active store of the NC indirectly via buffer stores. Associated with these signals are:

- external tool offset
- mirror image
- external additive T0

If these functions which are actuated in the active program are to be effective in the block following their selection, the block buffer store must be emptied. Alternatively the selected control signal only becomes active several blocks later.

In each program the buffer store can be emptied by a single call-up of the subroutine L99. The subroutine L99 must be defined as follows:

```
L9900      LF
@ 31 M17  LF
```

### Example:

Activation of external tool offset, e.g. after measurement of the tool.

- |              |   |
|--------------|---|
| N15 M...     | - PLC takes away input enable with the help of M function and transmits the external tool compensation. |
|              | - Afterwards PLC gives input enable again   |
| N20 G04 X... | - Dwell time is bigger than 1,2 x max. PLC cycle time   |
| N25 L99      | - Empty buffer store  |




## 5.7 Branch Conditions

The  $\textcircled{a}$  symbol is produced by pressing the  $\boxed{\frac{7}{\%}}$  key and the  $\boxed{\frac{\cdot}{R}}$  key.

### 5.7.1 $\textcircled{a}$ 00 Unconditional jump

Application: Program sections may be omitted using the unconditional jump.  
Blocks skipped are not processed.

Programming:



Different branch destinations can be achieved by using an R parameter with sign. An application of this special case is shown as follows:

Branch destination located before (-) branch operation

Standard case	Special case
<p>.</p> <p>.</p> <p>→ N98 X.. Y..</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>← N215 (a) 00 - 98</p> <p>.</p>	<p>R01 has, for example, the value 1</p> <p>N98 X.. Y..</p> <p>→ N99</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>← N215 (a) 00 - 98 R01</p> <p>.</p>

Branch destination located after (+) branch operation

Standard case	Special case
<p>.</p> <p>.</p> <p>← N215 (a) 00 + 280</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>→ N280 X.. Y..</p> <p>.</p> <p>.</p> <p>.</p>	<p>R01 has, for example, the value 1</p> <p>← N215 (a) 00 + 280 R01</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>.</p> <p>→ N280 X.. Y..</p> <p>→ N281 G04...</p> <p>.</p> <p>.</p>

Note: Branch destinations must always be blocks with a block number. This also applies, when the branch destination is varied by the R parameter.

Branch operations require time (max. 10 msec. per block skipped).


5.7.2 @ 01, @ 02, and @ 03 Conditional jump

Application:

Branch operations may be executed according to the following conditions:

equal @ 01  
 greater @ 02  
 greater or equal @ 03

Programming:



Operation with conditional jump

Branch destination is located before (-) or after (+) the branch operation:

The control searches for the branch destination in the given direction

Block no. of the branch destination: max. 4 digits

R parameter comparison for the conditional jump:

1st parameter equal to 2nd parameter @ 01  
 1st parameter greater than 2nd parameter @ 02  
 1st parameter greater or equal to 2nd parameter @ 03

1st parameter — — — —  
 2nd parameter

Different branch destinations can be achieved by using an R parameter with sign. An application of this special case is shown as follows:

Branch destination located before (-) branch operation

Standard case	Special case
.	R10 has, for example, the value 2
.	.
.	.
N98 X.. Y..	N98 X.. Y..
.	N99 M..
.	N100 X.. Z..
.	.
N215 @ <sup>=</sup> 01 - 98 R01 R02	N215 @ <sup>≥</sup> 02 - 98 R10 R01 R02
N216 G.. M..	N216 G.. M..
.	.
.	.

Branch destination located after (+) branch operation

Standard case	Special case
.	R15 has, for example, the value 5
.	.
.	.
N215 @ <sup>≥</sup> 03 + 280 R20 R25	N215 @ <sup>=</sup> 01 + 280 R15 R20 R25
N220 G.. M..	N220 G.. M..
.	.
.	.
.	.
N280 X.. Y..	N280 X.. Y..
.	N285 G04
.	.


Note: Branch destinations must always be blocks with a block number. This also applies, when the branch destination is varied by the R parameter.

### 5.7.3 Concluding example for unconditional and conditional jumps

Requirement:

A branch to 2 programs within a program

Flow chart:



Programming:

N005	G01	X..				
N010	@ 01	045	R10	R20		Conditional jump to program 2, if R10 = R20
N015						
N020						
N025						Program 1
N030						
N035						
N040	@ 00	070				Unconditional jump to block 70, in order to skip program 2
N045						
N050						
N055						Program 2
N060						
N065						
N070	G00	X..				

5.8 @ 10 "Square root"

1)


Application: Extract square root

Programming:

@ 10      R..

Operation: extract square  
root

R parameter for value  
assignment and result



Example:

N10 R10 25

R10 is loaded with 25

.

.

.

N75 @ 10 R10

Extract square root of the value  
defined in R10

N80

R10 has the value 5 from the  
next program block (here N80)

Note:

- Only positive values are to be entered
- Largest value 999999999.
- Smallest value .00000001

1) Only with basic control 3, 4


5.9 @ 15 "Sine" 1)

Application: Calculate the sine of an angle

Programming: @ 15 R..

Operation: calculate sine

R parameter for value assignment and result



Example:

N10 R17 45

R17 is loaded with 45

.  
.  
.

N75 @ 15 R17

Calculate sine of value stored in R17.

N80 .

R17 contains the value .7071067 from the next program block (here N80)

.  
.

Note:

- Positive and negative values are permitted
- Largest value +359.99999
- Smallest value -359.99999

1) Only with basic control 3, 4

5.10 @ 18 "Arctan" 1)


Application: Determination of an angle using the arctan function

Programming: @ 18 R ...

Operation: calculate arctan

R parameter (Rn) for value assignment  
b and result

R parameter (Rn+1) for value assignment



n = Parameter number

Example:

N10 R10 20 load 20 in R10 (b)  
N15 R11 30 load 30 in R11 (a)  
N20 @ 18 R10 Arctan calculation  
R10 = + 33.69007° Result is in R10

1) Only with basic control 3, 4




5.11 a 20 "load address parameter" 1)

Application: During measurement cycles for instance, it is necessary not only to program the numerical values of words as variables, but also the axis addresses. By varying the axis addresses the measurement cycle can operate in all NC-axes. Similar values for the number values (R00 to R99) of several address parameters @ 90 to @ 93 are available. @ 20 issues the statement to the NC, to load and address the parameter with the address code (see table below).

Axis	Address code
X	1
Y	2
Z	3
4.	4

Programming:

a) Load address parameters @ 90 to @ 93 by direct specification of address code via the axis No. (machine data)



1) Only with basic control 3, 4

b) Load address parameters @ 90 to @ 93 by indirect specification of the address via R parameter

N... @ 20 @ 93 + R49 LF

R49 is loaded with the address code of the required axis before execution of this block.

The address is allocated to the specified address parameter (@ 90 to @ 93) using this program. The axis direction can be reversed if required using the sign.

5.12 @ 90 to @ 93 "address parameter"

1)

Application: Parameter for axis addresses, so that not only numerical values but also addresses can be programmed as variables. Instead of axes X and Z, the address parameters are programmed.

Programming in the user program.

Example:

a) Address parameter without R parameter assignment.

N... @ 90 + 12345.678 LF

Address parameter defined  
e.g. as Y axis.

Sign for the axis value

Axis value

b) Address parameter with R parameter assignment.

Instead of a fixed numerical value, the axis value can be entered via an R parameter.

N... R01 12345.678 LF

Value assignment

1) Only with basic controls 3, 4

Application: Flexible access to the system memory locations of the NC control are possible from the user program with this function. The contents of the system memory can be read and other values can be entered into the system memory in some cases (loaded).

Access to following system memory locations is possible:

- Actual tool offset no.
- Tool offset
- Adjustable zero offset
- Programmable additive zero offset
- Current offset
- R parameters
- Machine data
- Machine data bit
- Actual values
- Background memory
- Special-purpose bit
- External zero offset (additional compensation)
- Measuring values

Note: If, for example, the programmable zero offset (G 59) is to be changed, @ 31 must have been programmed previously. This is always necessary if @ 29 is used to change system data which influence the paths to be traversed.

1) Only with basic controls 3, 4

Programming:

N... @ 29

1 63 01 R17 LF

Operation: load/read from  
the system memory

(own block)

1st position: 1 = read system memory  
location  
2 = load system memory  
location  
3 = read machine data  
bit

2nd + 3rd position: No. of R parameter (here R63).  
The value read is stored in  
this R parameter or the value  
from this R parameter is  
loaded in the system memory  
location.

4th + 5th position: Memory area coding  
01 = Tool geometry  
03 = adjustable zero offset  
04 = programmable additive  
zero offset  
08 = current offset  
09 = R parameter  
10 = Machine data  
12 = Actual value  
18 = Background memory  
19 = Special bit  
20 = Current tool correction No.  
13 = External zero offset (additional  
compensation)  
34 = Value store for measuring data

R parameter No. (here R17).  
The contents of this R parameter  
are a 4-decade coded number and  
specify the required memory from  
the memory area defined by @ 29,  
positions 4 + 5.

1st + 2nd position: e.g. axis number (for further  
explanations see overview p. 5 - 26)

3rd + 4th + 5th position: Identifying number e.g. number of the  
settable zero offset (for further  
explanations, see p. 5 - 26).

Example:

Application: The R parameter R01 is loaded during a gauging cycle with zero offset values for axis Z. This measured value is to be loaded into the system memory of the 3rd zero offset group in the SINUMERIK 3T.

Programming:

.  
. *read show*  
. *1003 R05*  
N50 R07 1 @ 29 10409 R07  
N55 R05 1003 @ 29 20403 R05  
. *2000 A*  
. *2000*  
. *X G50*

Explanation of the R parameters

R01	165.015	New zero offset value of Z axis
R04		contains the value to be transferred
R05	1003	Coding @ 29 (1st axis, 3rd zero offset group)
R07	1	Coding for @ 29 (R parameter No.) ( leading zeros can be suppressed).

# Overview of possible memory access operations (max. values)

e.g. N100 RAB 1 2 3 4 5 LF  
 N110 @ 29 1 2 3 4 5 RAB LF

Position 1	Meaning	Position 2 & 3	Meaning	Position 4 & 5	Meaning: System memory area for	Position 1 & 2	Meaning	Position 3 & 4 & 5	Meaning
1 or 2	Read location Write location	00 to 99	max. 100 R pars.	01	Tool com- pensation	01 02	Length Radius	001 to 064 1)	max. 64 groups 1)
1 2	Read Write	00 to 99	max. 100 R pars.	03	Settable zero offset	01 02 03 04	1st axis 2nd axis 3rd axis 4th axis	001 to 004 012	4 groups for 4B\4C 12 groups
1 2	Read Write	00 to 99	max. 100 R pars.	04	Programmable additive zero offset	01 02 03 04	1st axis 2nd axis 3rd axis 4th axis	001	1 group
1	Read	00 to 99	max. 100 R pars.	08	Current offset (Tool offset) (also mirrored) + zero offset	01 02 03 04	1st axis 2nd axis 3rd axis 4th axis	001	1 group
1 2	Read Write	00 to 99	max. 100 R pars.	09	R parameters	00 00 to 04	<small>No significance (up to basic version 4B)</small> <small>R parameter Group No. (from basic version 4C)</small>	000 to 099	100 numbers
1	Read	00 to 99	max. 100 R pars.	10	Machine data	00	no signif.	100 to 479 2)	380 2) numbers
3	Read bit	00 to 99	max. 100 R pars.	10	Machine data bit	00 to 07	Bit no.	400 to 479 3)	80 3) numbers
1	Read	00 to 99	max. 100 R pars.	12	Actual value	01 02 03 04	1st axis 2nd axis 3rd axis 4th axis	001	1 group
1 2	Read Write	00 to 99	max. 100 R pars.	18	Background memory	00	no signif.	000 to 099	100 numbers
3	Read bit	00 to 99	max. 100 R pars.	19	Special bit	00 to 07	Bit no.	001	1 group
1	Read	00 to 99	max. 100 R pars.	20	Current tool offset number	00	no signif.	001	1 group
1 2	Read Load	0 0 to 9 9	max 100 R pars.	1 3	External zero offset (addi- tional compens.)	01 02 03 04	1st axis 2nd axis 3rd axis 4th axis	0 0 1	1 group
1 2	Read Load	0 0 to 9 9	max. 100 R pars.	3 4	Value store	00	no signif.	0 0 0 to 0 9 9	100 value store numbers

\* Bit 0 : 1 = block active  
 Bit 1 : 1 = trial run active  
 Bit 2 : 1 = switching sensor swung out

Bit 3 : 1 = G70 active  
 Bit 4 : 1 = Simulation active (from 4C)  
 Bit 5 to 7: Unassigned


RAB is a freely selectable R parameter (AB = 00 to 99). RAB defines the system memory location to be read or to be loaded.

- 1) Basic control 3: 32 possible groups
- 2) Basic control 3: 100 ... 419 = 320 numbers
- 3) Basic control 3: 400 ... 419 = 20 numbers

## 5.14 @28 Selecting the R parameter group (only basic version 4C)

**Application:** This function can be used to select one of the groups 0 to 4 for the R parameters. Each group has 100 R parameters (R 00 to R 99).

**Programming:**



With power On, reset and M02/M30, group 0 is automatically selected.

An exchange of values over group limits is possible with function @29.

**Example:** R66 from group 0 is to be loaded with the value from R77 from group 1.

N5 @28 0	Selection group 0
N10 R10 01077	RAB assignment (R10) with R77 from group 1
N15 @29 26609 R10	@29 Read R parameters Target = R66, source = R77 (Address for source in R10)



## 6 Programming aids


### 6.1 Automatic insertion of chamfers and radii

At corners a chamfer or a radius can be inserted automatically. Examples 1 and 2 show the basic elements.

P-... means the insertion of a chamfer

P... means the insertion of a radius

#### 1 Chamfer




N... X<sub>2</sub>... Y<sub>2</sub>... P-...

N... X<sub>3</sub>... Y<sub>3</sub>...

The inserted chamfer must not be bigger than the smaller one of both distances.

#### 2 Radius




N... X<sub>2</sub>... Y<sub>2</sub>... P...

N... X<sub>3</sub>... Y<sub>3</sub>...

The inserted radius must not be bigger than the smaller one of both distances.

$\overline{X_2 Y_2, X_3 Y_3}$  or  $\overline{X_1 Y_1, X_2 Y_2}$


Example



N10	G00 G90 G42 X80. Y30.	LF (P2)	The value of P- or p must be < than the programmed dimension of the block in which it is to become active.
N15	Z-10.	LF (P2)	
N20	G91 G01 Y10.	LF (P3)	
N25	X-10.	LF (P4)	
N30	Y.10 P-5.	LF (P5)	
N35	G64 X-40. P18.	LF (P6)	
N40	X-10.Y-40. P5.	LF (P7)	
N45	X20. P5.	LF (P8)	
N50	G60 Y10.	LF (P9)	
N55	X30. P-5.	LF (P10)	
N60	Y10.	LF (P11)	
N65	X10.	LF	
N70	G00 G90 G40 X90. Y15.	LF (P1)	
N75	Z10.	LF	
N80	M02	LF	

### 6.1.1 Miscellaneous and auxiliary functions in linked blocks

A block is considered to be linked to an adjacent block when a radius or chamfer is used to connect the two blocks.



A block containing miscellaneous and auxiliary functions may be programmed between linked blocks.

Example: see above and example 6 - 1

```

N45 X20 P5 LF      (contour definition P7 - P8)
N46 M.. LF
N50 Y10

```

The miscellaneous functions become effective at the end of the block (i.e. P8 )(see above).

Free-cutting will result in P81.


Within the contour definition, G60 is automatically generated by the control at abrupt transitions (inserted chamfer).

This inserted G60 is not active as the reset position of the 10th G-group.

## 6.1.2 Example: Rectangular pattern

The following subroutine describes a rectangular pattern with variable rectangle sides, corner radii and depth advance. The radius parameter R03 must be smaller than R01, or one half of R00.

### Example:



### Subroutine:

```

L6 100
G42 D18 X... Y.... LF
N0 G01 G91 G64 Z-R02 LF (A)
N1 G02 X-R04 YR04 IO. JRO4 LF (P1)
N2 G01 YR01 PRO3 LF (P2)
N3 X-R00 PRO3 LF (P3)
N4 Y-R01 LF (P4)
N5 Y-R01 PRO3 LF (P5)
N6 X R00 PRO3 LF (P6)
N7 Y R01 LF (P1)
N8 G02 X R04 Y R04 I R04 JO. LF (E)
N9 G01 Z R02 LF (E)
N10 M17

```

### Subroutine call:

```

N25 G90 LF
N30 L6101 R00 60. R01 20. R02 5. R03 10. R04 10. LF

```

## 6.2 Blueprint programming (basic control 4B, 4C)


Blueprint programming means to directly input multi-point cycles according to the workpiece drawing. Intersections of straight lines are input as coordinate values or as angles.

The individual linear motions can have a direct transition in the form of a corner, they can be rounded by radii or chamfered. Chamfer and transition radii are input only using their size. The geometrical calculation is made by the control. The end point coordinates are programmed in absolute or incremental dimensions.

Angle (A): Input unit  $0.00001^\circ$

The angle (max.  $359.99999^\circ$ ) is always related to the positive axis vector with the highest address and to the positive direction of the other axis.

Address sequence: Z - Y - X




### Caution:

The blueprint programming is effective in the selected plane. 3D-machining is not possible. If there are four axes, the programmed axis must be the main axis.

## 6.2.1 Contour cycle programming

Examples 1 to 8 represent basic elements of the contouring cycle programming. These basic elements can be combined.


### 1. Two-point cycle



N...A...X<sub>2</sub>... (or Y<sub>2</sub>)

The second end position coordinate is calculated by the control


### 2. Circular arc



N..G02 (or G03) I..J..P..X<sub>2</sub>  
(or Y<sub>2</sub>)

The circular arc is limited to one quadrant. The second end position coordinate is calculated by the control. In the contour cycle, both parameters I and J must be programmed even if the value is zero.

### 3. Three-point cycle



N...A<sub>1</sub>...A<sub>2</sub>...X<sub>3</sub>...Y<sub>3</sub>


The control calculates the intersection coordinates (X<sub>2</sub>, Y<sub>2</sub>) and generates 2 blocks. The angle A<sub>2</sub> refers to the non-programmed support point (X<sub>2</sub>, Y<sub>2</sub>).

#### 4. Chamfer

N... X<sub>2</sub>... Y<sub>2</sub>... P-...

N... X<sub>3</sub>... Y<sub>3</sub>

P-... means insertion of a chamfer. the "Minus" character here does not mean a sign, but specifies P as chamfer.




#### 5. Radius

N... X<sub>2</sub>... Y<sub>2</sub>... P...

N... X<sub>3</sub> \*

The radius inserted must be smaller than the smaller of the two distances


$\overline{X_2Y_2}, \overline{X_3Y_3}$  or  $\overline{X_1Y_1}, \overline{X_2Y_2}$ .



#### 6. Straight line - circular arc (tangential)


N..G02 (or G03) A..P..X<sub>3</sub>..Y<sub>3</sub>..

Circular arc below 180°. The sequence A (angle) and P (radius) must be kept.



\* Second block may also be a contour cycle.


7. Circular arc - straight line (tangential)



N..G02 (or G03) P..A..X<sub>3</sub>..Y<sub>3</sub>..

Circular arc below 180°. The sequence P, A must be kept. No radius in X<sub>3</sub>, Y<sub>3</sub>.

8. Circular arc - circular arc (tangential)




N..G02 (or G03) I<sub>1</sub>..J<sub>1</sub>..I<sub>2</sub>..J<sub>2</sub>..X<sub>3</sub>..Y<sub>3</sub>

circle 1


The preparatory function is always programmed just for the first circular arc. The second preparatory function is contrary to the first one.

(1.) + (4.) Two-point cycle + chamfer



N.. A..X<sub>2</sub>... (or Y<sub>2</sub>...)  
P...N.. X<sub>3</sub>..Y<sub>3</sub>... \*

(1.) + (5.) Two-point cycle + radius




N.. A..X<sub>2</sub>... (or Y<sub>2</sub>...)  
P...N.. X<sub>3</sub>..Y<sub>3</sub>...

The radius inserted must be smaller than the shorter one of the two movements.

\* Second block may be also a contour cycle.




(3.) + (4.) Three-point cycle + chamfer




N... A<sub>1</sub>...A<sub>2</sub>...X<sub>3</sub>...Y<sub>3</sub>...P-...

(3.) + (5.) Three-point cycle + radius



N... A<sub>1</sub>...A<sub>2</sub>...X<sub>3</sub>...Y<sub>3</sub>...P...

(3.) + (4.) + (5.) Three-point cycle + chamfer + chamfer




N15 A<sub>1</sub>...A<sub>2</sub>...X<sub>3</sub>...Y<sub>3</sub>... P-...

P<sub>2</sub>-...

N16 X<sub>4</sub>... Y<sub>4</sub>... \*

Insertion of a second chamfer at the end position (X<sub>3</sub>, Y<sub>3</sub>).

(3.) + (5.) + (5.) Three-point cycle + radius + radius



N15 A<sub>1</sub>... A<sub>2</sub>... X<sub>3</sub>... Y<sub>3</sub>... P..


P<sub>2</sub>..

N16 X<sub>4</sub>... Y<sub>4</sub>... \*

Insertion of a second radius at the end position X<sub>3</sub>, Y<sub>3</sub>.

\* Second block may be also a contour cycle.


(3.) + (4.) + (5.) Three-point cycle + chamfer + radius



N.. A<sub>1</sub>..A<sub>2</sub>..X<sub>3</sub>..Y<sub>3</sub>..P-..P<sub>2</sub>  
..  
N16 X<sub>4</sub>..Y<sub>4</sub>

Insertion of a radius  
at the end position X<sub>3</sub>, Y<sub>3</sub>.  
The following block is  
automatically taken into  
account.

(3.) + (5.) + (4.) Three-point cycle + radius + chamfer



N15 A<sub>1</sub>..A<sub>2</sub>..X<sub>3</sub>..Y<sub>3</sub>..P..P-..  
N16 X<sub>4</sub>..Y<sub>4</sub>..

Insertion of a chamfer  
(P-) at the end position.

\* Second block may be also a contour cycle.

Corners without chamfer or radius must be programmed with 0 if there is another radius or chamfer in the contour cycle.

Caution:

In this programming, the control generates a block with the path = 0. This must be particularly observed if the cutter radius compensation is active.

B-0 is interpreted as B 0.

A radius or a chamfer may be inserted if the following block is no circular block.

The sequence of the addresses A, X, Y, P, F etc. can be freely selected, however, angles and radii must exist in the before-mentioned sequence (first angle before second angle, first radius before second radius in machining direction).

### 6.2.2 Operation of the function F, S, T, H, M in contour cycles

Within a contour cycle, the control automatically generates G60 at corners, edges etc. Here, the automatically inserted G60 function does not mean a reset of group 10.


If F, S, T, H, M are programmed in a contour cycle, they are effective at block start.

If M00, M02, M17, M30 are programmed in a contour cycle, they are effective at block end.

### 6.2.3 Chaining of Blocks

The chaining of blocks with and without angular input as well as with inserted radii or chamfer can be made in arbitrary sequence.

Example:




N10	Z...	P5	LF
N11	A...	X...	P7. LF
N12	A...	A...	X... Y... P9. P11. LF

## 6.2.4 Examples

The angle  $\alpha$  refers to the starting position, the angle  $\beta$  applies to the missing support point.

The end position can be programmed in absolute dimensions (G90) or in incremental dimensions (G91). Both end point coordinates must be started. The control then computes the support point using the starting position, the two angles and the end position.


Example:



```
:  
N10 G00 G90 X125. Y50. LF  
N11 G01 A280. A260. X47. Y58. F... LF
```

### Example: Contour cycle programming

In this example, the following contour cycles are used: Circular arc - circular arc, straight line - circular arc and a three-point cycle + chamfer + radius.




L16800

```
N1 G90 G03 I-10. J0. I0. J15. X105. Y25. LF (P2) Circular arc
      - circular arc
N2 G03 A315. P18. X40. Y50. LF (P3) Straight line
      - circular arc
N3 G01 A180.A90.X140.Y10.P-20.P10. LF (P4) three-point cycle
      + chamfer + radius
N4 Y40. LF (P1) straight line
N5 M17 LF
```

In block N2 G03 must be programmed since the second circular direction in the transition: circular arc - circular arc is opposed to the direction of the first circle (contour cycle 8).

## 6.2.5 Miscellaneous and Auxiliary Functions in Chained Blocks

Chained blocks are all blocks which share transitions with radii or chamfers.




Between chained blocks, it is possible to input a block with miscellaneous and auxiliary functions.

Example: see above and page 6 - 10.

```
N3 A180. A90. X140. Y10. P-20. P10 LF (contour cycle P3-P4)
N4 M... H... ..... LF
N50 Y40. LF
```

The auxiliary functions are activated in point P4 (see above). Accordingly, release cutting is done at point P41.





## 7. Cycles

### 7.1 Drilling/Boring Cycles G81 - G89

A boring cycle (working cycle) defines in accordance with DIN 66025) a series of machine movements necessary for drilling, boring, tapping, etc..

The boring cycles G81 to G89 are stored in the control as subroutines L81 to L89.

Canned cycle		Traverse rate into the part after positioning to the reference plane	At hole bottom		Retract to the reference plane	Application example
No.	Subroutine		Dwell	Spindle		
0	L800	-	-	-	-	Cancels L81-L89
1	L8100	in feed	-	-	in rapid trav.	Drilling, centering
2	L8200	in feed	yes	-	in rapid trav.	Drilling, counter-sinking
3	L8300	in interrupted feed	-	-	in rapid trav.	Deep hole drilling, chip breaking
4	L8400	feed per revolution	-	rev.	in rapid trav.	Tapping
5	L8500	in feed	-	-	in feed	Boring 1
6	L8600	Spindle on, in feed	-	stop	in rapid trav.	Boring 2
7	L8700	Spindle on, in feed	-	stop	manual retr.	Boring 3
8	L8800	Spindle on, in feed	yes	stop	manual retr.	Boring 4
9	L8900	in feed	yes	-	in feed	Boring 5

The user may deviate from a standard fixed cycle and re-define it to suit his specific machine or tooling requirements. The parameters R00 to R11 are used by the subroutine to define the variable values necessary to correctly execute a fixed cycle (e.g. reference plane coordinates, the hole depth, feed rate, dwell time, etc.). Prior to a subroutine call, all necessary parameters must be defined in the main program.

A fixed cycle call is initiated with G80 to G89. G81 to G89 are modal fixed cycles that are cancelled with G80. A boring cycle can be called with L81-L89, however, L81 to L89 are not modal. L81-L89 is performed only once in the block in which it is programmed. At the end of a fixed cycle the tool is repositioned at the starting point.

The following R parameters are used in cycles L81 - L89

R00 Dwell time at the start point (deburr hole)  
R01 First depth advance (incremental) entered without sign  
R02 Reference plane - retract plane (absolute)  
R03 Final depth  
R04 Dwell time at hole bottom (break chips)  
R05 Depth advance modifier entered without sign  
R06 Reverse spindle rotation direction  
R07 Return to the original spindle rotation direction  
used in the calling program (after R06 or M05)  
  
R09 Depth advance or thread lead modifier.  
R10 Retract plane  
R11 Boring axis (axis numbers X=1; Y=2; Z=3) 1)

The parameters are changed at the end of the cycle.  
The cutter must be positioned to the correct location in the  
plane perpendicular to the Z axis or to R11<sup>1)</sup> before calling.  
The appropriate feed, spindle speed, and rotation direction  
must be programmed for absolute dimensions. After a return from  
a fixed cycle incremental dimensions must be programmed again  
in the calling program.

Subroutine L80: (cancels G81 - G89)


G80 is an internal control function call.  
No parameter definitions are required.

1) with basic controls 3 and 4

Subroutine L81: (Drilling, centering)

The following parameters must be defined:


- R02 Reference plane (retract plane).
- R03 Final hole depth
- R11 Boring axis



Subroutine L82: (Drilling, counter sinking)

The following parameters must be defined:

- R02 Reference plane (retract plane)
- R03 Final hole depth
- R04 Dwell time
- R11 Boring axis




----- Rapid traverse

————— Feedrate

Subroutine L83: (Deep hole drilling)

The following R parameters must be defined prior to calling canned cycle L83:

- R00 Dwell at the start position (to deburr hole)
- R01 First depth advance (incremental) entered without sign
- R02 Reference plane = retract plane (absolute) "A"
- R03 Final hole depth (absolute)
- R04 Dwell time at hole bottom (break chips)
- R05 Incremental depth advance modifier entered without sign
- R11 Boring axis



R03 Final hole depth:

The incremental depth diminishes with each successive drill amount till the final hole depth R03 is reached. If the incremental depth advance modifier exceeds the actual drill advance, succeeding drill advances will be held constant. At the end of the drilling cycle the drill is brought to starting point A.

If the remaining depth is greater than R05 and less than 2 times R05, it is divided into 2 drilling strokes.

$$R05 < a < 2 R05$$


a = remaining depth

Subroutine L84:

(Tapping with spindle encoder)

The following R parameters must be defined:

- R02 Reference plane (retract plane)
- R03 Final depth
- R06 Spindle rotation reversal
- R07 Return to original spindle rotation direction.
- R09 Thread lead dimension
- R11 Boring axis




Subroutine L84:

(Tapping without spindle encoder)

The following R parameters must be defined:

- R02 Reference plane (retract plane)
- R03 Final depth
- R06 Spindle rotation reversal
- R07 Return to original spindle rotation direction.
- R11 Boring axis




Subroutine L85:

(Boring 1)

The following R parameters must be defined:

- R02 Reference plane
- R03 Final depth
- R10 Retract plane
- R11 Boring axis




----- Rapid traverse

————— Feedrate

Subroutine L86: (Boring\_2)

The following R parameters must be defined:


- R02 Reference plane
- R03 Final depth
- R07 Spindle on (after M05)
- R10 Retract plane
- R11 Boring axis



Subroutine L87: (Boring\_3)

The following R parameters must be defined:


- R02 Reference plane (retract plane)
- R03 Final depth
- R07 Spindle on (after M05)
- R11 Boring axis



Subroutine L88: (Boring\_4)

The following R parameters must be defined:

- R02 Reference plane (retract plane)
- R03 Final depth
- R04 Dwell time
- R07 Spindle on (after M05)
- R11 Boring axis



Fixed cycle L88 (G88) is similar to L87 (G87), however, a dwell is performed at the bottom of the hole.

----- Rapid traverse  
 \_\_\_\_\_ Feed rate

Subroutine L89: (Boring\_5)


The following R parameters must be defined:

R02 Reference plane (retract position)

R03 Final depth

R04 Dwell time length

R11 Boring axis



----- Rapid traverse

————— Feedrate


## 7.2 Examples of limitations in calling boring cycles

The drill cycle for every hole to be machined is called up only after the drill position has been reached.

The preparatory functions G81 to G89 can call up the sub-routines L8100 to L8900 for one cycle pass. At every drill position a called up cycle is activated; these cycles can be cancelled with G80. If comments are required for the cycles G81 - G89, these comments have to be written in blocks with position data. If one of these comments is written alone between 2 LF characters, a boring cycle will also be executed.

### Call-up G81 (Drilling, boring, centering, boring axis Z)

N8101	G90	S48	M03	F460	LF	- Spindle ON			
N8102	G00	D01	Z500.	LF	- Activate tool offset				
N8103	X100.	Y150.	LF	- 1st drill position					
N8104	G81	R02	360.	R03	250.	R11	3.	LF	- Call cycle
N8105	X250.	Y300.	LF	- 2nd drill position and automatic G81 call					
.									
N8110	G80	Z500.	LF	- Cancelling G81 and re-turning to starting plane					





Call with L81

```

N8101 G90 S48 M03 F460. LF
N8102 G00 D01 Z500. LF
N8103 X100. Y150. LF
N8104 L81 R02 360. R03 250. R11 3. LF - Call-up drilling
                                         cycle, 1st hole
N8105 X250. Y300. LF
N8106 L81 R02 . . . LF - Call-up drilling
. cycle, 2nd hole
.
N81.. Z500 LF

```


As opposed to the call-up with G81, here the drilling cycle must be called up anew at every new drilling position.

Call-up G82 (Drilling, countersinking, e.g. with variable boring axis)

```

N8201 ... M03 F460. LF
N8202 G00 D01 Z500. LF
N8203 X100. Y150. LF
N8204 G82 R02 360. R03 250. R04 1. R11 3. LF
N8205 X250. Y300. LF
.
.
N82.. G80 Z500. LF

```



Call L83 (Deep hole drilling)

First drilling depth	50 mm	R01	50.
Reference plane = retract plane	146 mm	R02	146.
Final drilling depth	5 mm	R03	5.
Dwell at starting point	5 s	R00	5.
Dwell at final depth	1 s	R04	1.
Degression value	20 mm	R05	20.
Drilling axis (Z)	3	R11	3.

N8301 ... S48 M03 F460.

LF

N8303 G00 D01 Z500.

LF

N8304 X100. Y150.

LF

N8305 G83 R01 50. R02 146. R03 5. R00 5. R04 1. R05 20. R11 3.


LF

N8306 X250. Y300.

LF

·  
·

N83.. G80 Z500.




At the rapid traverse advance respective to the new drilling depth, a safety distance of 1 mm is kept (on account of the chips still remaining in the hole).

With the inch system (G70) the safety distance must be changed accordingly.

Call-up G84 (Tapping for machines with spindle encoder)


N8401	...	S48	M03	F460.	LF
N8402	G00	D01	Z500.		LF
N8403	X100.	Y150.			LF
N8404	G84	R02	360.	R03 250. R06 04 R07 03 R09 5. R11 3.	LF
N8405	X250.	Y300.			LF
.					
.					
N84..	G80	Z500.			LF



Call G84 (Tapping for machines without spindle encoder)


```

N8401 ... S48 M03 F460. LF
N8402 G00 D01 Z500. LF
N8403 X100. Y150. LF
N8404 G84 R02 360. R03 250. R06 04 R07 03 R11 3. LF
N8405 X250. Y300. LF
.
.
N84.. G80 Z500. LF
  
```




Call G85 (Boring 1)

N8501	...	S48	M03	F460.	LF
N8502	G00	D01	Z500.		LF
N8503	X100.	Y150.			LF
N8504	G85	R02	360	R03 250. R10 380. R11 3.	LF
N8505	X250.	Y300.			LF
.					
.					
N85..	G80	Z500.			LF




Call G86 (Boring 2)

N8601	...	S48	M03	F460.	LF
N8602	G00	D01	Z500.		LF
N8603	X100.	Y150.			LF
N8604	G86	R02	360.	R03 250. R07 04. R10 380. R11 3.	LF
N8605	X250.	Y300.			LF
.					
.					
N86..	G80	Z500.			LF




Call G87 (Boring 3)

N8701 ... S48 M03 F460. LF  
N8702 G00 D01 Z500. LF  
N8703 X100. Y150. LF  
N8704 G87 R02 360. R03 250. R07 04 R11 3. LF  
N8705 X250. Y300. LF  
. LF  
N87.. G80 Z500. LF



Call G88 (Boring 4)


N8801	...	S48	M03	F460.	LF
N8802	G00	D01	Z500.		LF
N8803	X100.	Y150.			LF
N8804	G88	R02	360.	R03 250. R04 1. R07 04 R11 3.	LF
N8805	X250.	Y300.			LF
.					
.					
N88..	G80	Z500.			LF





Call G89 (Boring\_5\_)

N8901 ... S48 M03 F460. LF  
N8902 G00 D01 Z500. LF  
N8903 X100. Y150. LF  
N8904 G89 R02 360. R03 250. R04 1. R11 3. LF  
N8905 X250. Y300. LF  
.  
.  
N89.. G80 Z500. LF



### 7.2.1 Calling boring cycles in a subroutine

If boring cycles are called in a subroutine, the following procedure is necessary:

%

.  
.  
.

R02 360. R03 250. R00 81. R11 3. - Supply boring cycle parameters

L0101 - Boring positions

M30

L0101 (Boring positions)

G00 X1 Y1 - 1st Boring position

X2 Y2 - 2nd Boring position

X3 Y3 - 3rd Boring position

X10 - 4th Boring position

G80 M17 - Deselect boring cycle and  
end of subroutine

## 7.3 Listing of the boring cycles

### 7.3.1 Boring cycles G80-G89 for boring axis Z (basic controls 0, 1, 2)

E321	3M	0-2	GE	548811.2090.01 (old designation)
E822	3M	0-2	GE	548811.9102.01

X S P  
L8100 G G60 G90 Z R02 (10.03.83 [Z])  
G1 Z R03  
G Z R02 M17  
L8200 G G60 G90 Z R02  
G1 Z R03  
G4 F R04  
G Z R02 M17  
L8300  
R28 1  
G G60 G90 Z R02  
R01 R05  
R02 -R03  
Q03 4 R01 R02  
R01 -R05  
R02 R03  
R23 0 R01  
R24 0 R03  
R24 R05  
R22 0 R02  
N2 R22 -R23  
Q03 3 R24 R22  
G1 Z R22  
G4 F R04  
G Z R02  
G4 F R00  
R22 R28  
G Z R22  
R22 -R28  
R23 -R05  
Q03-2 R23 R05  
R23 0 R05  
Q00-2  
N3 R25 2  
R22 R23  
R22 -R03  
R22 /R25  
R03 R22  
G1 Z R03  
G4 F R04  
G Z R02  
G4 F R00  
R03 R28  
G Z R03  
R03 -R28  
R03 -R22  
G1 Z R03  
Q00 5

N4 R02 R03  
R01 -R05  
R02 -R01  
R26 0 R02  
G1 Z R26  
R02 R01  
G4 F R04  
G Z R02  
G4 F R00  
R26 R28  
G Z R26  
R26 0  
G1 Z R03  
N5 G4 F R04  
G Z R02 M17  
L8400 G G60 G90 Z R02  
G1 G63 Z R03  
M R06  
Z R02  
G G60 M R07  
M17  
L8500 G G60 G90 Z R02  
G1 Z R03  
G Z R10 M17  
L8600 M R07  
G G60 G90 Z R02  
G1 Z R03  
M5  
G Z R10 M17  
L8700 M R07  
G G60 G90 Z R02  
G1 Z R03  
M5  
M  
G Z R02 M17  
L8800 M R07  
G G60 G90 Z R02  
G1 Z R03  
G4 F R04  
M5  
M  
G Z R02 M17  
L8900 G G60 G90 Z R02  
G1 Z R03  
G4 F R04  
Z R02  
G M17  
L9000 G G60 G90 Z R02  
G33 Z R03 K R09  
Z R02 K R09 M R06  
G M R07  
M17  
L9900  
Q31 M17  
M02

7.3.2 Boring cycles G80 - G89 for boring axis Z

(basic controls 3, 4, 4B, 4C)

E321	3M	3-4	GE	548815.2090.01	(old designation)
E822	3M	3-4B	GE	548815.9101.01	

ZSP

L8100 G G60 G90 Z R02 (10.03.83[Z13])

G1 Z R03

G Z R02 M17

L8200 G G60 G90 Z R02

G1 Z R03

G4 F R04

G Z R02 M17

L8300 R78 1

R63 0 R07 R64 0 R01 R65 0 R67 2

R63 -R03

R67 .R05

G G60 G90 Z R02

N3 R63 -R64 R62 0 R03

Q03 4 R65 R63

R62 R63

G1 Z R62

G4 F R04

G Z R02

G4 F R00

R62 R78

Z R62 -R78

Q03 4 R05 R63

R64 -R05

Q02-3 R64 R05

R64 0 R05

Q03-3 R63 R67

R64 0 R63 R62 2

R64 /R62

Q00-3

N4 G1 Z R03

G4 F R04

G Z R02 M17

L8400 G G60 G90 Z R02

G1 G63 Z R03

M R06

Z R02

G G60 M R07

M17

L8500 G G60 G90 Z R02

G1 Z R03

G Z R10 M17

L8600 M R07

G G60 G90 Z R02

G1 Z R03

M5

G Z R10 M17

L8700 M R07

G G60 G90 Z R02

G1 Z R03

M5

M

G Z R02 M17

L8800 M R07

G G60 G90 Z R02

G1 Z R03

G4 F R04

M5

M

G Z R02 M17

L8900 G G60 G90 Z R02

G1 Z R03

G4 F R04

Z R02

G M17

L9000 G G60 G90 Z R02

G33 Z R03 K R09

Z R02 K R09 M R06

G M R07

M17

L9900

031 M17

M02

### 7.3.3 Boring cycles G80/G89 with variable boring axes

(Basic controls 3, 4, 4B, 4C)

E321	3M	3-4	GE	548815.2091.01	(old designation)
E822	3M	3-4B	GE	548815.9101.01	

— ZSP  
L8100 (10.03.83[VAR])  
@20 @92 R11  
G G60 G90 @92 R02  
G1 @92 R03  
G @92 R02 M17  
L8200  
— @20 @92 R11  
G G60 G90 @92 R02  
G1 @92 R03  
— G4 F R04  
G @92 R02 M17  
L8300 R78 1 R65 0 R67 2  
R64 0 R01 R63 0 R02 R66 1  
@20 @92 R11  
R67 .R05  
R63 -R03  
— @03 2 R63 R65  
R66-1  
N2 R63 .R66  
— R78 .R66  
G G60 G90 @92 R02  
N3 R63 -R64  
@03 4 R65 R63  
— R63 .R66 R62 0 R03  
R62 R63  
G1 @92 R62  
— G4 F R04  
G @92 R02  
G4 F.R00  
R62 R78  
— @92 R62 -R78  
R63 .R66  
@03 4 R05 R63  
— R64 -R05  
@02-3 R64 R05  
R64 0 R05  
— @03-3 R63 R67  
R64 0 R63 R62 2  
R64 /R62  
@00-3  
— N4 G1 @92 R03  
G4 F R04  
G @92 R02 M17  
— L8400  
@20 @92 R11  
G G60 G90 @92 R02  
G1 G63 @92 R03  
— M R06

092 R02  
G G60 M R07  
M17  
L8500  
020 092 R11  
G G60 G90 092 R02  
G1 092 R03  
G 092 R10 M17  
L8600  
020 092 R11  
M R07  
G G60 G90 092 R02  
G1 092 R03  
M5  
G 092 R10 M17  
L8700  
020 092 R11  
M R07  
G G60 G90 092 R02  
G1 092 R03  
M5  
M  
G 092 R02 M17  
L8800  
020 092 R11  
M R07  
G G60 G90 092 R02  
G1 092 R03  
G4 F R04  
M5  
M  
G 092 R02 M17  
L8900  
020 092 R11  
G G60 G90 092 R02  
G1 092 R03  
G4 F R04  
092 R02  
G M17  
L9000 R77 3  
020 092 R11  
G G60 G90 092 R02  
002 3 R11 R77  
000 R11  
N1 G33 092 R03 I R09  
092 R02 I R09 M R06  
000 5  
N2 G33 092 R03 J R09  
092 R02 J R09 M R06  
000 5  
N3 G33 092 R03 K R09  
092 R02 K R09 M R06  
N5 G M R07  
M17  
L9900  
031 M17  
M02



## 7.4 Keyway milling pattern L94

(Requirement: polar coordinates, Option B63)

(Reading/loading from system memories, option B76)

When programming only the subroutine L94 is called and the subsequent parameters are assigned values.

R04 \*\* Feed (depth)

R15 \*\* Feed (surface)

R01 Infeed (incremental without sign)

R02 Reference plane in absolute dimensions

R03 Keyway depth in absolute dimensions

R22, R23 MP-Midpoint of the slot referred to tool zero

R24 Radius


R25 Starting angle (referred to the horizontal axis)

R26 Indexing angle, if zero is selected as the indexing angle, then the number of keyways is subdivided accordingly

R27 Number of keyways

R12, R13 Parameter for "keyways"

The milling cutter diameter may not exceed a maximum of 0.9 of the keyway width!



\*\* Basic control 4B, 4C

Siemens AG Order No. 6ZB5410-0AM02-0BA0


E0888

7-25

## 7.5 Milling rectangular shape, subroutine L95

(Requirement reading/ loading from system memories, Option B76  
 Insertion of chamfers and radii, Option C33 or B75)  
 When programming, only subroutine L95 is called and the subsequent  
 parameters are assigned values. The machining plane must be defined  
 in the main program.

\*\* R11            Boring axis (variable plane)  
 \*R04            Feed (depth of pocket)  
 \*R15            Feed (surface of pocket)  
 R01            Infeed (incremental without sign)  
 R02            Reference depth in absolute dimensions  
 R03            Depth of pocket in absolute dimensions  
 R06            Milling direction cw/ccw (02/03)  
 R22/R23        Midpoint of the shape referred to tool zero  
 R12/R13        Dimensions of shape X/Y  
 \*\*R24           Radius



MP = Mid-point of pocket  
 \* Basic control 4 from cycle revision .02 onwards  
 \*\* Basic control 4B from NC-Software version 03 onwards

The tool follows the path shown after infeed in the part  
(optional clockwise or anticlockwise milling R06 = 02/03).

The path is parallel to the outer edges of the shape and adds  
a maximum of  $\sqrt{2} \cdot r$  ( $r$  = cutter radius) to these edges.

If the shape cannot be milled due to a too large cutting force  
requirement for infeed in the tool axis, then the infeed depth  
must be selected. The milling process repeats itself until the  
required depth has been reached. If R01 = 0, then the maximum  
infeed is immediately selected.

Subroutine L95 automatically selects the cutter radius compensa-  
tion when required. This can lead to contour deviations during  
single block operation.

If the milling cutter diameter exceeds half the length of the  
shorter side of the pocket, the subroutine is not executed.

There is a jump to the end of the program.

Subroutine L95 operates without CRC. The shorter side of the  
pocket must be at least 1 mm greater than the cutter diameter.

Radius R24 must be at least 0.5 mm smaller than half the length  
of the shorter side (R12, R13). \*\*

From basic control 4 onwards, the "cycle lock" signal on the  
interface must be active, and the limit of the R parameter  
display (machine parameter 382) must be set to  $\geq 50$ .


\* Basic control 4

\*\* Basic control 4B from NC-software version 03 onwards, 4C

## 7.6 Milling circular shape

(Requirement: reading/loading from system memories; Option B76)  
When programming, only the subroutine L96 is called and the subsequent parameters are assigned values.

R04	Feed (depth of pocket)
R15	Feed (surface of pocket)
R01	Infeed (incremental without sign)
R02	Reference plane in absolute dimensions
R03	Depth of pocket in absolute dimensions
R06	Milling direction cw/ccw (02/03)
R22/R23	MP midpoint of the shape referred to tool zero
R24	Shape radius
**R11	Boring axis (variable plane)



MP = Mid-point of pocket  
A = CRC select  
B = CRC cancel  
S = Any desired starting point with selection of tool length compensation  
\*\* Basic control 4B, 4C

The tool follows the spiral path shown after boring in to the part. The path spirals outwards at infeed  $\sqrt{2} \cdot r$  (r = cutter radius) (optional clockwise or counter-clockwise milling R06 = 02/03). If the shape cannot be milled due to a too large cutting force requirement for infeed in the tool axis, then the infeed depth must be selected. The milling process repeats itself until the required depth has been reached.

If R01 = 0, then the maximum infeed is immediately selected.

Subroutine L96 automatically selects the cutter radius compensation when required. This can lead to contour deviations during individual block operation. If the product of the milling cutter radius multiplied by 1.414 exceeds the radius of the pocket, the subroutine is not executed. There is a jump to the end of the program. \*

Subroutine L96 operates without CRC. The radius of the pocket must be 1 mm greater than the cutter radius. \*\*

From basic control 4 onwards, the "cycle lock" signal on the interface must be active and the limit of the R parameter display (machine parameter 382) must be set to  $\geq 50$ .

\* Basic control 4

\*\* Basic control 4B from NC-software version 03 onwards, 4C

## 7.7 Drilling/boring patterns

### 7.7.1 Subroutine: Boring pattern L97

(Requirement: polar coordinates, Option B63)

When programming, only the subroutine L97 is called and the subsequent parameters are assigned values after the parameters for the desired boring cycle have been programmed.

R22, R23      MP midpoint of the boring pattern referred to work-piece zero

R24            Radius


R25            Starting angle (referred to the horizontal axis)

R26            Indexing angle, if zero is selected as the indexing angle, then the number of holes is subdivided accordingly

R27            Number of holes

R28            Number of the boring cycle required (81-89)

\*\*R11          Boring axis (variable plane)



\*\* Basic control 4B, 4C

#### Subroutine call

```
N1900 L97 R22.. R23.. R24.. R25..  
          R26.. R27.. R28..      LF  
N1901...
```


7.7.2 Subroutine: Boring/Drilling pattern L93 (up to basic control 4B)

Subroutine: Boring/Milling pattern L904 (basic control 4C)

If identical operations are required at a large number of points at regular intervals on a workpiece (boring/drilling patterns, cycles) they can be entered as a pattern in a simple block. The points are then approached in sequence. There the boring/drilling cycle containing the required operation is called. The tool moves from point to point in a straight line. The point pattern can be parallel or at an angle to the coordinate axes.

When programming, only subroutine L93 is called and values assigned to the parameters after the parameters have been programmed for the boring/drilling cycle.

- R22/R23 Distance
- R24 Number of bores (first row)
- R25/R26 Distance
- R27 Number of bores (second row)
- R28 Required boring/drilling cycle (81-89)
- R11 Boring axis (variable plane)




## 7.8 Subroutine Milling pattern for elongated hole L98

(Requirement: polar coordinates, Option B63)

(reading/loading from system memories; Option B76)

When programming only the subroutine L98 is called and the subsequent parameters are assigned values.

\*\*R04      Feed (depth)  
\*R15      Feed (surface)  
R01      Infeed (incremental, without sign)  
R02      Reference plane  
R03      Depth of elongated hole  
R22,R23   MP midpoint of milling pattern referred to workpiece zero  
  
R24      Radius  
R25      Starting angle (referred to the horizontal axis)  
R26      Indexing angle, if zero is selected as the indexing angle, then the number of elongated holes is subdivided accordingly.  
  
R27      Number of elongated holes  
R12      Diameter of tool  
R13      Total length of elongated hole  
\*R11      Boring axis (variable plane)



\* Basic control 4

\*\* Basic controls 4B, 4C




8. Appendix

8.1 Cutter radius compensation

In the following all stop points are designated by an S.


8.1.1 Selecting the CRC

- Inside contours (the angle between blocks N10 and N11 is less than  $180^\circ$ ).




In a block following a block which selects the CRC, a vector of length R perpendicular to the programmed path is calculated.

- Outside contours (the angle between blocks N10 and N11 is less than  $270^\circ$  and greater than  $180^\circ$ ).




- Outside contours (the angle between blocks N10 and N11 is greater than  $270^\circ$ ).



### 8.1.2 CRC in the program


- Inside contour (the angle between two blocks is less than  $180^\circ$ )

Straight line - Straight line




The intersection of the cutter compensation path is calculated.

Circle - circle





- Outer contour (the angle between two blocks is less than  $270^\circ$  and greater than  $180^\circ$ )

Straight line - straight line




The intersection of the cutter compensation path is calculated.

Straight line - circle




At the arc end point A (or arc start point), a normal vector of length R is calculated. The intersection point is calculated from the tangent at point B and the cutter compensated path of N11 (or N10).

Circle - circle



At the arc end point (or arc start point), a normal vector of length R is created for both arcs. The tangent to point B1 - B2 is determined and the tangent - tangent intersection calculated.

Straight line - circle (the angle is greater than 270°)




At the end point and start point respectively of blocks N10 and N11, a normal vector of length R is calculated for each path. A compensating movement is made, whereby the distance of radius R is traversed past the programmed contour to prevent damage to the workpiece.

Changing the cutter compensation direction

At the block end point the old compensation direction (G41/G42) is changed to start the next block (G41/G42). The compensation direction is switched in the following manner:

Normal vectors of length R are calculated at the end point and start point of the new blocks respectively.



SP00089.2


## Changing the offset number (G41 D., G41 D..)

When changing the offset number, the following applies:

No block start intersection is calculated with the old offset value.


At the end point of the block with the old offset number, a normal vector of length  $R_1$  is calculated.

The end point of the block is calculated with the new offset.




## Changing the offset values

The offset values can be changed via the operator panel, punched tape, external tool offset or in the parts program. The new offset value is effective in the next block.



8.1.3 Repetition of G function already selected (G41, G42)  
with same offset number

If already programmed G41, G42 is repeated, a normal vector of length R is erected for the programmed path at the end point of the previous block.



For the following block, the block start intersection is calculated:



N4	G91	D10	G41	X....		LF
N5				X....		LF
N6				Y....		LF
N7	G41			X....	Y....	LF Error: G41 repeated!
N8				Y....		LF

### 8.1.4 Cutter radius compensation deselection


- Inside contour (the angle between blocks N10 and N11 is less than  $180^\circ$ ).

Straight line - straight line

Circle - straight line



Circle - circle




The last block in which CRC is active, a normal vector of length  $R$  is erected for the programmed path.

When a transition is made to a linear path, the programmed end point is approached directly.


When a transition is made to a circular path, a displaced arc path is traversed to the horizontal (or vertical) intersection point. The remaining distance is traversed along the horizontal (or vertical) to the end point.

If prior to reaching the horizontal (vertical) intersection path an end point coordinate is reached, the other coordinate is approached directly (see figure above).

- Outside contours (the angle between blocks N10 and N11 is less than  $270^\circ$  and greater than  $180^\circ$ )



(The angle between blocks N10 and N11 is greater than  $270^\circ$ )



The compensated path is calculated, the tool traverses to the next calculated intersection point of the block in which CRC is cancelled.



### 8.1.5 M00, M02, and M30 with CRC selected

M00: The NC stops at point S in the single block mode. (The positions are shown in the figures).

M02, M30: - The CRC is cancelled, if it is deleted with G40, and at least one axis is programmed.

```
N150 X.. Y.. LF
N200 G40 X.. M30 LF
```

- The CRC is not cancelled, if no path is programmed.

Example 1:

```
N150 X.. Y.. LF
N200 G40 LF
N250 M30 LF
```

Example 2:

```
N150 X.. Y.. LF
N200 M30 G40 LF
```

## 8.1.6 CRC with combination of different block types

The examples refer to the X-Y-plane.

Type: - Distances in the CRC - plane

Example:

```
N... G91 X1000. LF
```

- "Distance = 0"

Preparatory functions are programmed, no movements take place, because the distance is zero.

Example:

```
N... G91 X0. LF
```

- "Auxiliary functions"

No preparatory functions of the CRC-plane are programmed; instead only auxiliary functions, dwell or a zero offset are in the block.

Example:

```
N... Y1000 LF
```


```
N... M08 LF
```

```
N... G04 F10. LF
```

```
N... G59 X10. LF
```


```
N... T0101 LF
```

Two distances in the CRC-plane



N5	G91	X1000.	LF
N6		Y-1000.	LF


One "aux. function block" between distances in the CRC-plane



N5	G91	X10000.	LF
N6	M08		LF
N7		Y-1000.	LF

The block N6 is executed at point S.


Two "miscellaneous blocks" between distances in the CRC-plane



N5	G91	X10000.	LF
N6	M08		LF
N7	M09		LF
N8		X-10000.	LF
N9		X1000.	LF

The blocks N6 and N7 are executed at point S. With the exception of tangential transitions, contour errors result.


One block "distance = 0" between distances in the CRC-plane



```
N5 G91 X1000. LF
N6 XO. LF
N7 Y-1000. LF
```

With the exception of tangential transitions, contour errors result.


Two blocks "distance = 0" between distances in the CRC-plane



```
N5 G91 X1000. LF
N6 XO. LF
N7 XO. LF
N8 Y-1000. LF
```

With the exception of tangential transitions, contour errors result.


One block "distance = 0" and one "aux. function block" between distances in the CRC-plane



```
N5 G91 X1000. LF
N6 XO. LF
N7 M08 LF
N8 Y-1000. LF
```

With block N7 is executed at point P.  
With the exception of tangential transitions, contour errors result.

One "aux. function block" and one block "distance = 0" between distances in the CRC-plane




```

N5 G91 X1000. LF
N6 M08 LF
N7 X0. LF
N8 Y-1000. LF
    
```

The block N6 is executed at point S. With the exception of tangential transitions, contour errors result.

Two blocks between distances in the CRC plane




```

N1 G0 X0 Y0 Z100
N2 G41 X50 Y-50
N3 Z10
N4 Z0
N5 X75
N6 Y-100
    
```

The blocks N3 and N4 are executed at point S. Contour errors result, except on tangential transitions.


### 8.1.7 Special cases for CRC

Since the control always uses the information of the next block to calculate the intersectional path, a contour distortion will result under the following circumstances.




The tool offset dimension is larger than the distance between two paths. Machining is not interrupted, however, an alarm is signalled and again cancelled at the end of the program.

CRC direction is not changed but the traverse direction of the cutter is reversed.




The retract dimension N2 must be programmed at least twice the cutter radius amount, since the cutter's position relative to the part has been incorrectly defined. When the direction reversal takes place, the control will compensate by an amount twice the radius value in a direction towards the part.

For an outside contour with a circle to circle transition at an obtuse angle, the following applies:




To avoid transition paths, control generated, that are of such short time duration that axis motion is momentarily halted, paths AB and BC may be omitted.

Dependent on a dimension tolerance defined during set up (max. 32000  $\mu\text{m}$ ) the resultant generated path is as shown.



If  $\Delta X1$ , and  $\Delta Y1$  is less than  $d$ , the traversing is directly from A to C.




If  $\Delta X1$ ,  $\Delta Y1$ ,  $\Delta X2$ , and  $\Delta Y2$  are less than  $d$ , no path is generated.

Traversing is continued from A using the new radius.

When machining inner contours with selected cutter radius compensation, an acute-angular contour transition (programmed) and an axis which moves in the meantime but does not lie in the cutter radius compensation plane, a virtual change of the block numbers results on the display.

With this method the workpiece will not be damaged.



SP00295.0

```

N5   G00  Z100.
N10  X0.  Y10.
N15  G41  D01  X20.  Y20.
N20  G03  X0.  Y40.  I-20.  J0.
N25  X0.  Y40.  I0.  J-40.
N30  G01  Z0.
N35  G40  X80. Y60.

```

Logically, the points S1, S2, S3, S4 belong to block N25.

The sequence of machining (which is visible in the single block) is: ..., N20, N25 (S1), N30 (retracting tool from the workpiece), N25 (S2), N25 (S3), N25 (S4), N35...

This method is also applied, if N25 is a linear block.





## 8.2 Input system, digrams, and tables

### 8.2.1 Incorrect input of the interpolation parameters I, J, K

An arc end point programming error is recognized by the control (assuming the tolerance window is exceeded). Circular interpolation will not begin, instead, an alarm is signalled.

If the programming error lies within the arc tolerance window, the control will position accurately to the end point, however, the path will deviate from the desired arc as shown.


#### Interpolation parameter



The tolerance window T about the arc end point CE is adjustable from  $\pm 1 \mu\text{m}$  to  $\pm 32000 \mu\text{m}$ .

The monitor can be suppressed by setting a large dimensional value. The tolerance window is input as an unsigned dimension stored under a machine parameter address.

## 8.2.2 Reference points



M = Machine zero

W = Workpiece zero

R = Machine reference point

WR = Workpiece reference point

XMR, ZMR etc. = Reference point coordinates for each axis

XMW, ZMW etc. = Sum of all zero offsets for each axis

Total zero offset = settable offset (G54..G57) + additive zero offset (G59) + external additive zero offset (ext. suppl. offset)

8.2.3 Path calculation

G91 in the first program block with a motion dimension


$$\text{Distance} = \text{Incremental dimension} + Z0 + T0$$

G91 from the second program block with a motion dimension

$$\text{Distance} = \text{Incremental dimension} + Z0_{\text{new}} - Z0_{\text{old}} + T0_{\text{new}} - T0_{\text{old}}$$


If the Z0 and T0 are not changed, the following applies:

$$\text{Distance} = \text{Incremental dimension}$$




G90 in an arbitrary program block with a motion dimension

$$\begin{aligned} \text{Distance} = & \text{Absolute dimension}_{(\text{new})} - \text{absolute dimension}_{(\text{old})} \\ & + Z0_{(\text{new})} - Z0_{(\text{old})} + T0_{(\text{new})} - T0_{(\text{old})} \end{aligned}$$



## 8.2.4 Rotational feedrate limits



$n_{\max. 1}$  can be achieved with encoder connected 1:1  
 $n_{\max. 2}$  can be achieved with encoder connected 1:2

## 8.2.5 Input formats

Address definition	Metric		Inch		Degrees	
	Decades	Smallest increment	Decades	Smallest increment	Decades	Smallest increment
Path data (linear axes) Interpolation parameter	$\pm 5.3$ 1)	$10^{-3}$ mm	$\pm 4.4$ 1)	$10^{-4}$ in	-	$10^{-3}$ degrees
Path data (rotary axes)	-		-		$\pm 5.3$ 1)	
Chamfer (P-); Radius (P)	3.3		2.4		-	
Zero offset	$\pm 5.3$		$\pm 4.4$ 1)		$\pm 5.3$ 1)	
Thread pitch	3.3		2.4		-	
Spindle speed S (Weighting factor set during commissioning)	4.0	1 or $0.1 \text{ min}^{-1}$	4.0	1 or $0.1 \text{ min}^{-1}$		
Linear feedrate (F)	5.0	mm/min	3.1	$10^{-1}$	5.0	degrees/min
Rotary feedrate (F)	2.3	$10^{-3}$ mm/rev	1.4	$10^{-4}$ in/rev		
Tool offset	Length $\pm 3.3$	$10^{-3}$ mm	$\pm 2.4$	$10^{-4}$ in		
	Radius $\pm 3.3$		$\pm 2.4$			
Dwell	X	$10^{-3}$ sec		$10^{-3}$ sec		
	F		2.3			
Angle					3.5	$10^{-5}$ degrees
Angle for oriented spindle stop 3)					3.1	$10^{-1}$ degrees
R parameter	Dimension depends on associated address (internal floating point) all combinations (2 decades for call)					
G preparatory function	2		2			
M functions	2		2			
Block number	1 to 4		1 to 4			
H function	4		4			
Special functions @	2		2			
Factor P	3.5	$10^{-5}$	3.5	$10^{-5}$		

The parameters (R00-R99) <sup>2)</sup> are always to be written with 2 decades. For all other functions (except address L) the leading zeros can be omitted.

- 1) For basic control 0, 1, 2: 1 decade less before the decimal point
- 2) For basic control 0, 1, 2: R00-R49
- 3) Not with basic controls 0, 1, 2



### 8.3 Program key

Group	EIA	ISO	Code for basic control			Section	Function and meaning	
			0,1,2	3	4 / 4B,4C			
	EOR	o/o				1.	Program start	
	EOR ... EOB	o/o ... LF	1 ... 9999	1 ... 9999	1 ... 9999	1.7	Program number	
	n /n	N /N	1 .. 9999	1 ... 9999	1 ... 9999	1.4 1.4	Block number Skippable block	
	.	.				1.3	Decimal point	
	+	+					Positive sign (can be omitted)	
	-	-					Negative sign	
G1	g	G	00	00	00	3.2 3.3 3.18 3.18 3.4 3.4 3.5	Rapid traverse Linear interpolation Polar coordinate programming rapid traverse Polar coordinate programming linear interpolation Circular interpolation clockwise Circular interpolation counter- clockwise Thread cutting	
			01●	01●	01●			
			-	-	10			
			-	-	11			
			02	02	02			
			03	03	03			
			33	33	33			
					-	34	3.5.3.2	Thread cutting, pitch increasing linearly
					-	35	3.5.3.3	Thread cutting, pitch decreasing linearly
G2	g	G	■04*	■04*	■04*	3.9	Dwell time, time under F address	
G4	g	G	17●	17●	17●	3.13 3.13 3.13	Plane selection XY-plane XZ-plane YZ-plane	
			18	18	18			
			19	19	19			
G5	g	G	40●	40●	40●	3.15 3.15 3.15	Cancel cutter radius compensation Cutter radius compensation, left Cutter radius compensation, right	
			41	41	41			
			42	42	42			
G6	g	G	-	-	43●	3.16 3.16	Tool length offset positive Tool length offset negative	
			-	-	44			
G7	g	G	■53	■53	■53	3.11.3	Suppress the zero offsets	
G8	g	G	54●	54●	54●	3.11.1 3.11.1 3.11.1 3.11.1	Select zero offset 1 Select zero offset 2 Select zero offset 3 Select zero offset 4	
			55	55	55			
			56	56	56			
			57	57	57			
G9	g	G	■59*▲	■59*▲	■59*▲	3.11.2	Programmable additive zero offset	
G10	g	G	60●	60●	60●	3.6 3.8.1 3.7 3.8	Exact stop Continuous path mode via reduced speed Tapping with a compensation chuck Continuous path mode	
			-	-	62			
			63	63	63			
			64	64	64			
G11	g	G	70	70	70	3.10 3.10	Input system in inch Reset state via Input system in metric machine data	
			71	71	71			
G12	g	G	90●	90●	90●	3.1 3.1	Absolute dimension programming Incremental dimension programming	
			91	91	91			
G13	g	G	-	-	92	3.17	Factor for the unit circle with P	
			-	-	-	▲92*	3.5.4.2	Spindle-related starting angle offset under A
					-	▲92*	3.21	Smoothing exponent for thread under T
G14	g	G	94●	94●	94●	3.12 3.12	Feedrate under address F in .../min Feedrate under address F in .../rev.	
			95	95	95			
G15	g	G	80●	80●	80●	7.	No boring cycle Boring cycle	
			81 ...	81 ...	81 ...			
			89	89	89			
G16	g	G	-	-	-	3.19 3.19 3.19	Coordinate transformation OFF Coordinate transformation TRANSMIT "ON" Coordinate transformation "DOUBLE- TRANSMIT" ON	
			-	-	-			
					36● 37 38			

Program key (continued)

Group	EIA	ISO	Code for basic control			Section	Function and meaning
			0,1,2	3	4		
	s	S	1...99 1... 9999	1...99 1... 9999	1...99 1... 9999	4.1	Spindle speed (geometrical series) Spindle speed in rev/min or 0.1 rev/min
	t	T	1...99 1... 9999	1... 9999	1... 9999	4.2 4.2	Tool-No. Tool-No.
	d	D	01..32  00	01...32  00	01...32 01...64 1)  00	3.14  3.14	Tool offset number Tool length 999.999 mm 99.9999 inch Cutter radius 999.999 mm 99.9999 inch Suppress tool offset
	h	H	-	-	1...9999	4.4	Auxiliary functions
M1	m m	M M	00 02 17  30	00 02 17  30	00 02 17  30	4.3 4.3 4.3  4.3	Programmed stop, unconditional End of program End of subroutine, written in the last block of the subroutine End of program (see M02)
M2	m	M	03 04 05●  19■	03 04 05● 19■	03 04 05● 19■	4.3 4.3 4.3 4.3	Spindle start, clockwise Spindle start, counter clockwise Spindle stop Oriented spindle stop, angle under S in degrees
M3	m	M	00.. 99	00... 99	00... 99	4.3	Miscellaneous functions, unassigned except groups M1, M2
	l	L	01.. .. 99.. .. - - ..01.. ..99 ..01... ..99	01.. 99.. - - ..01... ..99 ..01... ..99	01.. ... 99.. 001.. 2) 999.. ...010... ...99 ...01... ...99	1.8    1.8	Subroutine numbers (L80-99, L900- L999) for Cycles    Number of repetitions
	@	@	00 01 02 03 31 - - - - - - -	00 01 02 03 31 10 15 18 20 90-93 29	00 01 02 03 31 10 15 18 20 90-93 29	5.7    5.6 5.8 5.9 5.10 5.11 5.12 5.13	Unconditional jump Conditional jump, equal Conditional jump, greater Conditional jump, greater or equal Empty buffer store Square root Sine Arctan Load address parameters Address parameters Load/read from system memory
	EOB	LF				1.4	End of block

1) With basic control 4 32 additional compensations as option

2) Only with basic control 4



## 8.4 Special cases

### 8.4.1 Special case "Delete distance to go"

The remaining setpoint-actual value difference (distance to go) of a programmed axis motion can be reset (erased) via an interface. The machine manufacturer determines which M function is used for activating and disabling the "delete distance to go" signal.

The axis, whose traversing motion was interrupted by the "delete distance to go" function, must have a G90 programmed in the subsequent block (absolute dimension programming). The programming procedure given below must be followed:

- empty buffer with                    Ⓐ 31
- load actual value with               Ⓐ 29
- travel to actual position with G90

#### Programming example

```
⋮
M..      - activate the "delete distance to go"
         function
G90 G01 X100 - Delete distance to go for X60
M..      - Deselect "delete distance to go"
         function
Ⓐ 31    - empty buffer
R00 1001 Ⓐ 29 19312 R00 - load actual value
G90 XR93 - travel to actual position
G00 G91 X 60 - travel to new position e.g. X 120
⋮
```

To  
Siemens AG

E 885  
Postfach 48 48  
D-8500 Nürnberg 1

**Suggestions**

**Corrections**

For Publication/Manual:

SINUMERIK 3M  
Basic Version 4C

Programming Guide

Order No.: 6ZB5 410-0AM02-0BA0  
Edition: 08.88

**Sender:**

Name \_\_\_\_\_

Company/Dept. \_\_\_\_\_

Address \_\_\_\_\_

Telephone / \_\_\_\_\_

Should you come across any printing errors when reading this publication, we would ask you to inform us accordingly, using this form. We would also welcome any suggestions you may have in the way of improvement.

**Suggestions and/or corrections**